

83
SHA
3356-7
1911-12
L

3356

&

Plat. No. 1506-2

3357

Department of Commerce and Labor

COAST AND GEODETIC SURVEY

Superintendent.

State: *Mass*

DESCRIPTIVE REPORT.

Hyd Sheet No. *3356-7*

LOCALITY:

Plum Id. Sound

" " River

1901-12

CHIEF OF PARTY:

E. B. Latham

B

3356-7

Hyd. 3356, 3357.

Department of
Commerce and Labor.

Coast and Geodetic Survey.
O. H. Tittmann, Superintendent

Hydrographic Sheet
Plum Island Sound and Tributaries
Ipswich River to
Merrimac River.

Scale 1-10,000

E. B. Latham, Assist. C. & G. S.
Chief of Party.
Apr. 1912

2 numbered sheets

Assistant in Charge.

L. A.

Hyd. 3356

" 3357.



Descriptive Report,

Superintendent.

Hydrographic Sheets, Plum Island Sound and Tributaries

This survey was made during September and October 1911 and March 25-27-1912. Soundings were made largely to utilize the time of my party, while engaged in the surveys of Ipswich and Plum Island Bars and when conditions presented work on these bars. As the ice carried down the banks and deposited much mud in the River Channel, the channels were sounded in March 1912, and the soundings plotted on separate sheets, on tracing paper. It is presumed that these soundings are to be used when offsetting from them in pencil on the main sheets.

Plum Island Sound is much used by gasoline pleasure boats. The Plum Island River affords a passage from the Merrimac into the Sound. A chart, published by the Harbor and Land Commission, State of Massachusetts, is transmitted with the sheet, as a part of the record. The only danger on the sheet, is Juncus and South Juncus rocks, just north of Juncus Creek. Plum Island Sound is buoyed by the Bureau of Lighthouses. A sketch sent to the Commissioner of Lighthouses, a few

was suggested to mark the Southern End of Rowley Spit.

Rowley River is reported as navigable for a short distance above the Boston and Maine Railroad bridge, but it is not advisable for a stranger to go above the town landing, about 300 meters below this bridge and near Rowley Station. The town of Rowley is about one mile from the station.

Ipswich River can be navigated up to the bridge at County Street, but it is advisable to go no further than the wharf at East Street, when during the summer a float is maintained for the convenience of motor boats. Gasoline, oil, and other supplies can be obtained here. During the summer a small steamer is operated between this wharf and points in Ipswich River and Plum Island Sound to Parker River, landing at Newbury (La Jona). There are two trips daily, except Sundays, each way.

Parker River is navigable for a distance of $5\frac{1}{2}$ miles above Newbury to Byfield. There are no draws in the bridges. There is a head way of 12 feet at Parker River and 10 feet at the Boston and Maine Railroad.

Supplies of all kind may be obtained at Newbury port. For a more extensive description of conditions

at Newburyport, see descriptive report of the
revision of Topographic sheet No 355.

E. J. Nathan

Asst. Chief of Party

Statistics Hydrographic Sheet

Plum Island Sound and Tributaries.

Date	Day	Vol.	No. Angles.	No. Sounds.	No. Miles.
Sept 20-11	A	1	112	482	9.50
Sept. 21-11	B	1	118	723	16.25
Sept 28-11	C	1-2	156	724	10.75
Oct 3-1911	D	2	104	537	8.75
Oct 6-11	E	2	126	600	10.0
Oct 11-11	F	3	50	1052	20.0
Oct 12-11	G	3	54	663	6.5
Mar 25-12	H	4	2	388	4.0
Mar 27-12	I	4	<u>20</u>	<u>236</u>	<u>3.0</u>
			712	5405	88.75

Soundings in feet.

Plane of ref. S. 6 Plum Id. Tide Gauge.

E. B. Saltham, Chief of Party

Note O day Mar 26th angles 20, Soundings 438
Miles 10.0 pertains to Sheet 3312 - a
duplicate set of notes, sent to the
office on loose sheets.

Department of Commerce and Labor

Aug 1, 1912

Library: - This letter should be filed with the descriptive report of Hyd sheet no. 3356

G.P.T.


To be acknowledged by
Library *over*

C. & G. SURVEY,
LIBRARY AND ARCHIVES
AUG 1 1912

Recd 2 angle books
 " Hyd Sheet
 " 3312 & boat "
 " 3356
 " 1 Tracing blue print 13785
 1 Sketch of Station. Volume
 of Tracing on paper

Post-Office Address: Portsmouth, N.H. 2 Hawthorn Street
Telegraph Address: _____

Express Office: _____



Department of Commerce and Labor
LIBRARY AND ARCHIVES
COAST AND GEODETIC SURVEY
AUG 1 1912
Acc. No.

RECEIVED
BY ASSISTANT IN CHARGE
AND REFERRED TO
AUG 1 1912
D.T.Z. M.S.

Portsmouth, N.H.
July 30, 1912

Superintendent
Assistant in Charge.

Superintendent, C&G
Coast and Geodetic Survey
Washington D.C.

ANSWERED
AUG 5 - 1912

Sir:

LIBRARY AND ARCHIVES

I return, under separate cover, the records mentioned in your letter of July 25-1912, with tracing and sketch showing adjustment of position of stations, at the juncture of sheets 3312 and 3356. With certain angles, observed during the topographic ^{revision}, added to the record in the angle book.

The position of the signals north of Lee, Up, etc do not depend on them or on Lee, Dal, etc, but were determined on separate data, that is, on Old Town triangulation and other triangulation stations on the shores of Plum Island Sound.

When 3356 was plotted, the positions on 3312 were not available, stations Hill Bar, Torr, 1910 were plotted on 3356, and these positions checked with the work of 1911 - and it was assumed that the work on the two sheets agreed. Station Up, when checked

with the determinations of 1910 and 1911 show a discrepancy. The determination of 1910 of this station is weak, depending on Hill Inn and Bar. The discrepancy is such, that it is believed that it will not be necessary to replot the soundings in a scale of 1:20,000 (sheet 3312). The sounding records are not available to test this. It is suggested that the sounding lines north of Hill and west of Win. be plotted to test this, preferably on No 3356 - Scale 1-10,000.

The order of plotting sheet 3356 is as follows -
1- Plotting of triangulation stations - 2. Plotting of theodolite angles observed at Old Inn and other triangulation stations, and at Topo. Signal, Red. Bee stations to be controlled by these lines. Station Dal-
Plotted on the line from Old Inn triangulation station with the angle Jel-Hill - (Jel is a true theodolite angle line.) and tested with other stations. Also during the topographic revision, angles were observed between Old Inn triangulation, Ipswich and Rowley Church and Hill, this position checks well with the previous determination. It would probably give a better determination, to use the angle Old Inn Ipswich Church, but the discrepancy is within an allowable discrepancy. Exact angles at Bar, check its 1910 position, with stations Life Sav. Sta Cupola, Old Inn and Jel, and indicates that Hill

should be 10 metres north of its 1910 position. Station up 1910, depending on Hei Bar and Joo, with stations Min and Ho. depending on its position were not accepted, but were replotted. See tracing showing lines and adjusted position for this station, and for new positions for Min and Ho. The shore line depending on the position of Up and Min, was replotted. (See sheet and tracing) this being as the topography affected.

The discrepancies noted in your letter of July 18, were caused by the poor position of Up, and the enlarging from 1-20,000 to 1, 10,000 and expanding or locating stations from the signals of 1910, when a better determination controlled the signals on sheet No 3356 as plotted in the field.

The tracings submitted and the angles when plotted on sheet 3356-, will show that all stations are well located and that the topography in Plum Island Sound and River is not affected, further than noted and corrected.

Respectfully

E. S. Sattam

Assist. C. P. Surveyor

Chief of Boats

VEC
May 10, 1912.

HYDROGRAPHIC SHEET 335C.

Plum Island Sound, Massachusetts, by Asst.
E. B. Latham in 1911.

TIDES.

	Bluff Wharf ft.
Mean low water, or plane of reference on staff	4.6
Lowest tide observed " "	4.5
Highest " " " "	14.9
Mean range of tide	8.7

~~West and Corlette Survey~~
MAY 16 1912
TIDAL DIVISION.

VEC
May 10, 1912.

HYDROGRAPHIC SHEET 3357.

Plum Island Sound, Massachusetts, by Asst.
E. B. Latham in 1911.

TIDES.

	Bluff Wharf ft.
Mean low water, or plane of reference on staff	4.6
Lowest tide observed " "	4.5
Highest " " " "	14.9
Mean range of tide	8.7

Coast and Geodetic Survey
MAY 16 1912
TIDAL DIVISION

Hyd. Sheet No. 3356

An examination of this work, showed plainly that some essential feature was in error.

After the soundings were plotted, that portion of Hyd. Sheet No. 3312, which overlaps this work, was enlarged to this scale. The hydrography disagreed so badly, that a further enlargement and comparison was made, bringing out the fact that the tri. point, "Ipswich L. H.," is shown in an old and abandoned position, on this sheet, although correct on Hyd 3312, and that the hyd. signals, common to both sheets, were shown in different positions on each. A list of these signals was made and forwarded to Asst. Latham, who sent in a tracing showing their correct position, as re-determined. The hydrography on hyd. sheet No. 3312, was badly affected; therefore, that portion controlled by these signals, was retracted and plotted on this sheet. Also the lines on this sheet, most affected by the changed positions of signals, were retracted and plotted.

The soundings on the three tracings, of the Parker, Rowley and Ipswich Rivers, were transferred to this sheet and the work on them given preference over that on the main sheet, where ever it conflicted. (Desc. Report.) These tracings may now be treated as boat sheets.

This is not reliable work and is not of much

value, except to give a general idea of the ground. The only thing which can be said favorable of it, is that the ground is very well covered.

The work in the Parker, Rowley and Ipswich Rivers, is especially questionable, as it has practically no control. No angles were read on positions and such positions as were described, could hardly be plotted from the character of descriptions given. These lines had to be accepted in the position shown on the sheet by the field party and adjusted to cross as well as possible.

The main body of the work is also unreliable, the crossings poor, records not well kept and the protracting and plotting that was done is inaccurate. The letters on some of the lines did not correspond with those in the records.

The manner in which some of the hyd. signals, on the lower part of the sheet, are shown, is somewhat misleading. Two separate positions are shown, one marked 1911 and the other 1912. There is only one correct position for each signal, generally the one in black (1912), which was used for all work.

R. L. Johnston

Nov. 1912.

Oct 8, 1914

Hyd. Sheet No. 3357

As positions on sounding lines were not determined so they can be checked and many positions could not be identified all that could be done was to ink in the soundings where they were placed in pencil by the field party. No verification of the plotting is possible.

Channel lines were not run and the survey did not develop the water that can be carried through the waters covered by the survey

G.S.H.