

8039

Diag. Cht. Nos. 5802 & 5902-2

Form 504

C-356

U. S. COAST AND GEODETIC SURVEY

DEPARTMENT OF COMMERCE

DESCRIPTIVE REPORT

Type of Survey HYDROGRAPHIC

Field No. WCFP-05153 Office No. H-8039

LOCALITY

State OREGON

General locality NEWPORT

Locality YACUINA BAY

1945

CHIEF OF PARTY

C. J. Beyma

LIBRARY & ARCHIVES

DATE

B-1870-1 (1)

8039

DEPARTMENT OF COMMERCE

U. S. COAST AND GEODETIC SURVEY

HYDROGRAPHIC TITLE SHEET

The Hydrographic Sheet should be accompanied by this form, filled in as completely as possible, when the sheet is forwarded to the Office.

REGISTER No. 8039

Field No. WCFP 05153

State OREGON

General locality NEWPORT

Locality YAQUINA BAY

Scale 1/ 5 000 Date of survey 1 April to 21 August 1953

Instructions dated 2 March 1953

Vessel Launch CS-160

Chief of party C.J. Beyma

Surveyed by C.J. Beyma & G.E. Haraden

Soundings taken by ~~fathometer~~ graphic recorder, hand lead, wire

Fathograms scaled by Party Personnel

Fathograms checked by C.J. Beyma & G.E. Haraden

Protracted by H.C. Parsons

Soundings penciled by H.C. Parsons

Soundings in ~~fathoms~~ feet at ~~MLW~~ MLLW *and are true depths*

REMARKS: Plotted in Seattle Processing Office.

DESCRIPTIVE REPORT TO ACCOMPANY HYDROGRAPHIC SURVEY

H-8039 (1953)
 H-8040 (1953)
 H-8041 (1953)

Field Sheet (WCFP 05153)
Field Sheet (WCFP 1153)
 Field Sheet (WCFP 1253)

YAQUINA BAY OREGON AND APPROACHES

Project CS-356
 West Coast Field Party
 Surveyed by C. J. Beyma, G. E. Haraden

Season of 1953
 C. J. Beyma, Chief of Party

A. PROJECT

The work was done in accordance with instructions for project CS-356 dated 2 March 1953.

B. SURVEY LIMITS AND DATES

The limits of this survey include Yaquina River and Approaches and extend from latitude $44^{\circ} 34.0'$ to latitude $44^{\circ} 41.0'$ and from longitude $123^{\circ} 55.6'$ to longitude $124^{\circ} 07.0'$. *Includes adjacent surveys*

Field work was begun 1 April 1953 and was completed 16 October 1953. Work in Yaquina Bay and River progressed satisfactorily, however considerable trouble was encountered in the adjacent offshore area. Progress was retarded by unfavorable weather and the fact that the launch used was unsuitable for sounding on the unprotected coast. Sounding on the reef immediately north of the jetties was unsafe because of the presence of continuous breakers during the working season.

C. VESSEL AND EQUIPMENT

The hydrography was performed exclusively with launch CS-160 which operated from a shore base at Newport, Oregon. The turning radius of the launch was approximately 30 meters. Fathometers of the 808 type were used. Fathometer number 152SPX was used at all times except when inoperative, in which case number 154SPX was substituted until repairs could be made.

D. TIDE AND CURRENT STATIONS

Two portable recording tide gages and one tide staff were used in connection with this survey. A tide gage at the U. S. Coast Guard Station in Newport was maintained throughout the entire working season for reducing soundings obtained on sheets H-8039 and H-8040. A tide gage at Yaquina was also maintained throughout the entire working season and was used for reducing soundings on that portion of Sheet H-8041 which is west of longitude $123^{\circ} 58'$. For the remainder of Sheet H-8041 a tide staff at Toledo, Oregon was used.

D. TIDE AND CURRENT STATIONS, CONTD.

Five current stations were occupied as follows:

- (1) On the north side of the channel under the highway bridge between Newport and South Beach, observations for 100 hours.
- (2) Near the docks at Newport near the West Junction Buoy, observations for 100 hours.
- (3) Off Yaquina, observations for 97 hours.
- (4) Between the jetties near the entrance to Yaquina Bay, observations for 9 1/2 hours.
- (5) Three tenths miles north of Light 47, Yaquina River, observations for 29 hours.

H-8039

E. SMOOTH SHEETS

Smooth sheets for this survey are to be drawn and completed by the Seattle Processing Office.

F. CONTROL STATIONS

Positions of hydrographic signals and triangulation stations used for the control of this survey were furnished by the Portland Photogrammetric Office. Photo-hydro signals were transferred to the boat sheets by pricking through photographic manuscripts T-11136, T-11137 and T-11138. Refer to Descriptive Report, Project Ph-113 for further details regarding control for this survey.

*H-8039

Seven hydrographic signals were located by planetable methods. Refer to Descriptive Report covering Topographic sheet WCFP-A-53.

D.R. in
H-8040

Hydrographic signals ROC and POLE were located by four sextant cuts from the launch at various positions south of Yaquina Head. These cuts are recorded in Volume II pages 29 and 30, H-8040.

Hydrographic signals HEX and KEY were located by measuring along the Boat Basin breakwater from the Boat Basin Lights. These distances are recorded in Volume I page 3, H-8039.

No difficulty was encountered with any of the control signals.

G. SHORLINE AND TOPOGRAPHY

All shoreline for this survey was furnished by the Portland Photogrammetric Office and transferred to the boat sheets from Manuscripts T-11136, T-11137 and T-11138, by the West Coast Field Party.

*H-8039

G. SHORELINE AND TOPOGRAPHY CONTD.

The low water line in Yaquina Bay and Yaquina River is adequately defined. On the outside coast it was impossible to delineate the low water line because of alongshore breakers.

H. SOUNDINGS

Fathometer 152SPX and 154SPX when received from the Washington office were equipped with 820 fms/sec. tachometers. 800 fms/sec. tachometers were requisitioned from Washington early in May but were received by the party late in June. The 820 fms/sec. tachometers were used in fathometers 152SPX and 154SPX on boat sheet H-8039 from 3 June 1953 thru 10 June 1953 day letters a, b, c, d, e, and f. On boat sheet H-8040 the 820 fms/sec. tachometer was used on 12 June 1953 day letter a. On subsequent days 800 fms/sec. tachometers were used on boat sheets H-8039, H-8040 and H-8041.

The fish on the keel of the launch was used on boat sheet H-8039 letter days a thru g and on boat sheet H-8040 on letter days a and b. On June 26, 1953 an outboard fish was installed on the launch. The reason being that the fish attached to the keel gave unsatisfactory results especially when sounding on the outside coast. The launch has a ramp bow, because of its design when sounding on the coast, the launch would ride over every swell causing air to pass under the keel resulting in large void sections on the fathograms. To rectify this an outboard fish was installed on the starboard quarter of the launch to enable this party to sound at a greater speed and thus take advantage of favorable weather on the open coast. Because of the construction of the launch the conventional type bar could not be used advantageously, so a fathometer receiver was used in taking bar checks. By lowering the receiver unit directly under the outboard fish attached to a graduated wire rope, a value of 1.0 feet was found to give good results when taking a bar check. This value was then doubled and adopted as initial setting, thus eliminating any index correction while sounding.

After sounding for two days on Sheet H-8040 b and c days and h day on Sheet H-8039 it was discovered by using 2.0 as an initial setting the fish would ground before the launch and a reading of less than three feet recorded on the fathogram. The bottom of the housing enclosing the fathometer units was measured with a steel tape to be 38 inches below the surface of the water. A bar check was taken with a conventional metal bar suspended below the fish and the bar check corroborated that ^{the} initial setting should have been 3.2 feet in lieu of 2.0 feet as recorded on the fathograms for h day on sheet H-8039 and c and d days on Sheet H-8040. *"c and d" days*
 Handlead soundings were taken against fathometer soundings also pole soundings against fathometer soundings all indicating the initial to be 3.2 feet. So an index correction of +1.2 feet was applied to the soundings obtained on those days. Why the unit gave erroneous bar checks yet consistent thru the range of depths of the A Scale cannot be accounted for unless for the reason that the unit was kept out of the water and not soaked well enough to give the correct results.

H. SOUNDINGS CONTD.

Since the outboard fish grounded before anything else it was advisable to raise it to a point which was less than the draft of of the launch. On 6 July the fish was raised to 27 inches below the water surface. Subsequent bar checks indicated the new initial to be 2.2 feet. Both type bar checks that is the metal bar, and the receiver unit gave the same results. After h day Sheet H-8039 the receiver unit used in taking bar checks was submerged in a large can of sea water at all times, to allow the unit to become well soaked.

On Sheet H-8040 it was impossible to obtain satisfactory bar checks with an ordinary metal bar. The sea action and under water currents would cause the bar to move in every direction except under the fish. The receiver unit was used successfully on the A Scale only. When switching to the B Scale the fathogram consistently indicated a shoaler depth of 2 feet throughout the B Scale range. On the C Scale range there was no correction. The fathogram and the measured depth on the receiver unit agreed; likewise on the D Scale. By anchoring the launch in the Bay in a depth of about 40 feet the A Scale and B Scale agreed, so no phase correction was applied to the soundings on the B Scale. To determine the phase correction on the C and D Scales the launch was allowed to drift and comparative readings were taken on the B and C Scales and similary on the C to D Scales. On the C Scale the correction was -1.2 feet and D Scale -2.6 feet. These corrections were obtained by scanning the peaks and troughs on either scales and obtainning a mean. It was accepted for about 75% of the survey that the bar checks on the various fathometer scales were correct by using the fathometer receiver unit as a bar until it was decided to actually check the scales by bottom comparison. It was discovered that the receiver unit was registering erroneously on the B, C and D Scales in comparison with the depth of the bottom recorded on the fathograms on the various scales. Attempts were made to check the bottom comparison with a leadline. Because of the sea and wind conditions the leadline could not be read accurately. It was impossible to obtain a vertical depth with the leadline or to accurately average the height of the swells. The leadline would be either leading aft or inboard or outboard. To record such a reading would only introduce additional errors.

*Not applicable
to present
survey*

Weather conditions on the outside coast were far from ever being calm. Even what was considered calm to accomplish launch hydrography, the seas were 4 to 6 feet high. By inspecting the fathograms it can be clearly seen the conditions of the seas while sounding on the outside coast. On many days the fathograms cannot be scanned to average the correct depth within 2 feet. It seems impracticable to make any corrections to the soundings except for tide because of the prevailing weather conditions this season along the Oregon Coast.

Temperature and salinity observations were not observed principally because every workable day on the coast was utilized in launch hydrography. During the entire season there were so few days that a launch could actually work on the coast. Even these days were rough, far from what one would consider calm or ideal for launch hydrography.

I. CONTROL OF HYDROGRAPHY

Sextant fixes, using the three point method, were used for horizontal control of the survey, except for sounding lines in the sloughs at Oysterville. Lines run in these sloughs were midchannel lines and only the times when abeam signals and times of all turns were recorded for control data. Sextant fixes were not taken because sufficient signals were not visible when needed and the angles changed too rapidly when they were visible. In the western slough at Oysterville the boat sheet soundings were plotted by dead reckoning.

H-8041

Soundings from position 89 - 90 of ^{"F" DAY} H-8039 were rejected because of a 13 foot sounding which plotted out of place. The area was thoroughly developed on an overlay, on 21 August 1953, q day, and the 13 foot sounding was not found.

J. ADEQUACY OF SURVEY

Survey Sheets H-8039 Yaquina Bay, and H-8040 Yaquina River, are adequate and complete and should supersede prior surveys for charting. Boat Sheet H-8040 is adequate for navigation purposes, however, due to the prevailing heavy seas and strong NW'ly winds, the offlying reef could not be thoroughly developed. Shoal soundings from prior surveys should be retained for charting.

Junctions with prior surveys H-4894 and H-4749 were made on the west and north with considerable overlap and depth curves can be adequately drawn.

K. CROSSLINES

A total of 7.6% crosslines were run on Sheet H-8041 Yaquina River with very good agreement.

Crosslines to the extent of 7.4% were run on Sheet H-8039 Yaquina Bay, with generally good agreement except for crossings between the jetties. The system of short lines between the jetties and normal to the channel should be adjusted when smooth plotted allowing for the launch to attain sounding speed and spacing the soundings accordingly.

crossings
in agree-
ment on
smooth sheet.

On Sheet H-8040 7.6% of the total mileage was crosslines. All crossings were in good agreement.

L. COMPARISON WITH PRIOR SURVEYS

H-8041

There are no recent prior surveys of Yaquina River, however comparison with Sheet H-3728, 1914 scale 1:10,000 indicates that the river has shoaled from zero to three feet between Mc Lean Point and Toledo.

L. COMPARISON WITH PRIOR SURVEYS CONTDH-8039

Survey H-3727, 1914 scale 1:10,000 is obsolete and the only recent survey of this area is a condition survey by the U. S. Corps of Engineers. Engineers survey Sheet YB-1-249, scale 1:5,000 May 1953 agrees with soundings of this survey in the channel.

See
TPG of
Review

H-8040

Comparison with old survey H-4894, 1928, scale 1:40,000 is in good agreement at the junctions.

Survey H-4749, 1927, scale 1:20,000 is in good agreement, however shoaler depths were found on the reef west of and southwest of Yaquina Head.

Comparison with old survey H-4879, 1928, scale 1:20,000 is generally good except over the reefs. Shoaler soundings were obtained on the south reef and this reef was found to extend to the southern limits of the survey. The shoal soundings on the north reef north of Yaquina Reef Buoy 3 could not be verified because of breakers in that area.

M. COMPARISON WITH CHART

Comparison with Chart 6058, August 1942 (19th Edition), scale 1:20,000, reveals the following:

The area southwest of Boat Basin West Light has shoaled considerably as a result of the Engineers emptying their dredgings on the south side of the breakwater and the subsequent shifting in a westerly direction.

H-8039

The channel under the highway bridge has ^{scoured} shoaled up to five feet deeper than the depths on the published chart.

H-8034

The shallow channel southeast of McLean Point no longer exists. Construction is under way in that area at present.

H-8041

The slough at Oysterville extends south of the limits of Chart 6058 and is navigable by small boats. Lumber tugs haul log rafts through this slough to the mills along the Yaquina River. For this reason it is recommended that the limits of Chart 6058 be extended to include this slough.

H-8044

No indication of the sunken wrecks in latitude $44^{\circ} 36'$ Longitude $124^{\circ} 06'$ and Latitude $44^{\circ} 37'$ Longitude $124^{\circ} 06'$ was found during this survey.

H-8040

The sunken wreck charted at Latitude $44^{\circ} 36' 58''$ Longitude $124^{\circ} 05' 12''$ should be charted as stranded wreck bearing 5.5 feet at MLLW, see position data, Volume I, page 4, H-8040.

M. COMPARISON WITH CHART CONTD

The four foot rock charted at latitude 44° 37.6' longitude 124° 04.25' is misplaced. This survey indicated a shoal approximately 220 meters NNE of the charted position, see boat sheet H-8040.

Verification of the three foot rock south of the ^{South} jetty was not possible and therefore should be retained on the chart.

H-8040

Investigations of the charted shoal at latitude 44° 39.8' longitude 124° 05' indicates that the symbol as charted should be deleted. This shoal is a continuation of Yaquina Reef which runs from the entrance channel north to the limits of the survey.

The offshore reef on chart 6058 is so extensive that the many shoal soundings charted could well exist although all were not verified during this survey. It is therefore recommended that the shoal soundings from prior surveys be retained for charting.

The rocks west of Coquille Point and at latitude 44° 36.7' longitude 124° 00.7' were found as charted.

H-8041

The rock charted at latitude 44° 35.00' longitude 124° 00.32' should be shown as rocks awash baring 3.4 feet at MLLW.

No indications of the following charted features were found during the survey and they should be deleted from the chart:

Charted Feature	Latitude	Longitude
Rock Symbol	44° 39.8'	124° 05.0'
Chimney	44° 34.7'	124° 00.2'
Dolphin Rock	44° 37.31'	124° 02.01'
14 ft. Sdg.	44° 38.90'	124° 04.15'
2 ft. Rock	44° 36.6'	124° 04.42'

omit Review H-8041

H-8039 (See Review of H-8041)

N. DANGERS AND SHOALS

Newly found dangers within the limits of this survey include the following:

Sheet No.	Danger	Latitude	Longitude	Least Depth	Position No.
H-8040	Stranded Wreck	44° 37.32'	124° 04.78'	Bares 5.5 ft. @ MLLW	1 a
H-8041	Steel Boiler	44° 36.81'	124° 01.11'	Bares 3.8 ft @ MLLW	1 a
H-8041	Log	44° 34.47'	123° 59.47'	Bares 6.0 ft @ MLLW	6 q
H-8041	3 Logs	44° 34.34'	123° 58.97'	One End Floats	23,24 & 25 g

N. DANGERS AND SHOALS CONTD

Sheet No.	Danger	Latitude	Longitude	Least Depth	Position No.
H-8041	Log	44° 34.38'	123° 58.18'	One End Floats	67 g
H-8041	Log	44° 35.07'	123° 57.63'	" " "	26 h
H-8041	Log	44° 35.10'	123° 57.56'	" " "	27 h
H-8041	Log	44° 35.53'	123° 56.30'	" " "	63 j
H-8041	Stump	44° 36.71'	124° 01.44'	Bares 9.0 ft. @ MLLW	69 c

O. COAST PILOT INFORMATION

The following are corrections to Coast Pilot Notes for Yaquina Bay, Oregon Chart No. 6058. Page and line numbers refer to publication "United States Coast Pilot Pacific Coast Seventh (1951) Edition":

Page 326 Line 41; States "26 feet deep over the bar." The present survey indicates 22 feet least depth over the bar. | H-8040
(1953)

Page 327 Line 34; Strike out lines 34, 35 and 36. Insert - The controlling depth in Yaquina River to Toledo in August 1953 was 9 feet; In Depoe Creek the controlling depth was 3 feet in August 1953. | H-8039
(1953)

Page 328 Line 17; Strike out "The wharves have 10 to 12 feet alongside. Insert - The wharves have 5 to 6 feet alongside. | H-8041
(1953)

P. GEOGRAPHIC NAMES

All geographic names within the limits of this survey were investigated by the Portland Photogrammetric Party and a special report was submitted by that office. *Report on file - 854, L. Heck*

Submitted By

C. J. Beyma
C. J. Beyma
CDR., USC&GS

Approved & Forwarded

C. J. Beyma
C. J. Beyma
CDR., USC&GS
Chief of Party

8039
8040
8041

TIDE NOTE

Sheet H-8039

Field Sheet WCFP 05153

An automatic recording portable tide gage at latitude $44^{\circ} 37.55'$ longitude $124^{\circ} 03.30'$ was used to reduce the soundings for survey H-8039. Mean lower low water on the staff corresponds to a reading of 3.2 feet.

No corrections to the observed readings were applied for differences in time or height.

Sheet H-8040

Field Sheet WCFP 1153

The same tide gage at latitude $44^{\circ} 37.55'$ longitude $124^{\circ} 03.30'$ was used for the reduction of soundings on survey H-8040 as was used for H-8039. No corrections were applied for differences in time or height.

Sheet H-8041

Field Sheet WCFP 1253

Two tide stations were used for reducing the soundings for survey H-8041. A portable recording gage at latitude $44^{\circ} 36.17'$ longitude $124^{\circ} 00.57'$ was used for reducing all soundings on survey H-8041 west of longitude $123^{\circ} 58.00'$. Mean lower low water on the staff corresponds to a reading of 1.9 feet.

A tide staff at latitude $44^{\circ} 37.04'$ longitude $123^{\circ} 56.16'$ was used for reducing all soundings on this survey east of longitude $123^{\circ} 58.00'$. Mean lower low water on the staff corresponds to a reading of 3.4 feet.

No corrections for differences in time or height were applied to either the gage or the staff readings.

STATISTICS FOR HYDROGRAPHIC SURVEY H-8039

FIELD SHEET NO. WCFP 05153

LAUNCH CS-160

Project CS-356

Vol. No.	Day Letter	Date	No. HL Soundings	No. Pos.	No. Stat. Miles Sdg.
I	-	5/26/53	259	259	1.4
I	-	5/29/53	13	13	0.1
II	a	6/3/53	-	33	2.1
II	b	6/4/53	-	114	8.5
III	c	6/5/53	-	24	2.3
III	d	6/8/53	-	50	4.6
IV	e	6/9/53	-	93	7.8
IV & V	f	6/10/53	-	110	9.2
V	g	6/22/53	-	49	3.2
VI	h	7/2/53	-	73	4.4
VI & VII	j	7/6/53	-	153	10.1
VII	k	7/7/53	-	20	0.8
VII	l	7/21/53	-	124	9.0
VII & VIII	m	7/24/53	*	54	4.8
IX	n	8/17/53	-	28	Bottom Samples
IX	p	8/18/53	-	12	Bottom Samples
IX	q	8/21/53	-	47	2.2
TOTALS				1255	70.5
TOTAL SQUARE STATUTE MILES				0.94	

NAVIGATIONAL LANDMARKS FOR CHARTS

TO BE CHARTED
~~XXXXXXXXXXXX~~

STRIKE OUT ONE

I recommend that the following objects which have ~~(have not)~~ been inspected from seaward to determine their value as landmarks be charted on ~~(charts)~~ the charts indicated.
The positions given have been checked after listing by O. J. Bayne

Same as list 935 (1453)

O. J. Bayne

Chief of Party.

Report, Oregon

6 October 1953

STATE	OBJECT	DESCRIPTION	SIGNAL NAME	POSITION			METHOD OF LOCATION SURVEY NO.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED
				LATITUDE*	LONGITUDE*	D.P. METERS						
	RADIO MAST (WASTERLY OR TWO)	Support Radio Station (KIPR Tower)	STAR	44 39	170.3	124.03	29.6	1927	Trilateration			6098
	LIGHT HOUSE	Abandoned (Taquta Lighthouse, old)	HOUSE	44 37	850.9	124.03	926.3					6092 6093 6098
	LOOKOUT TOWER	House 9' x 9', 70' high on 49' elevation steel tower	LOOK	44 37	849.5	124.03	921.9					6092 6093 6098
	HARBOR (PIR 17)	Support, center of bridge, light	LIGHT	44 37	702.1	124.03	470.0					6092 6093 6098
	TANK	Silver, low elevated water condenser Top	RUN	44 37	23	123 56	1031	"	Radial Plot	1953	X	6098
	STACK (NORTHEAST OF T-2)	Black metal	TAN	44 37	11	123 56	541	"	"	1953	X	6098
	TANK (ELEVATED)	Black, on steel elevation	TAP	44 37	0	123 56	440	"	"	1953	X	6098

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.
* TABULATE SECONDS AND METERS

NON-FLOATING AIDS OBSOLETE FOR CHARTS

TO BE CHARTED
TO ~~XXXXXXXXXXXX~~

STRIKE OUT ONE

Newport, Oregon

8 October, 19 53

I recommend that the following objects which have (has) been inspected from seaward to determine their value as landmarks be charted on (delete) the charts indicated.
The positions given have been checked after listing by O. E. Haraden

Form and letter 935 (1953)

O. J. Boyes

Chief of Party.

STATE	CHARTING NAME	DESCRIPTION	SIGNAL NAME	LATITUDE *		LONGITUDE *		DATUM	METHOD OF LOCATION AND SURVEY NO.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED
				° ' "	D. M. METERS	° ' "	D. P. METERS							
		Approach Lighted Whistle Buoy #1*		44 35	1623	124 06	1010	MA 1927	Hydrographic Survey 68-336	6/12/53		X	X	5902 6098
		Distance Lighted Ball Buoy #1*		44 36	565	124 05	840	"	"	"		X	X	6098
		Distance Buoy #2*		44 36	761	124 05	214	"	"	"	X			6098
		Trigular Reef Buoy #9*		44 36	1151	124 04	1399	"	"	"	X			"
		North Jetty Gang Buoy #5*		44 36	1413	124 04	790	"	"	"	X			"
		Channel Lighted Buoy #7*		44 37	112	124 03	1410	"	"	6/3/53	X			"
		West Junction Buoy		44 37	1245	124 03	194	"	"	"	X			"
		Channel Buoy #9*	H-1039	44 37	1212	124 02	958	"	"	"	X			"
		Channel Buoy #11*		44 37	1111	124 02	548	"	"	"	X			"
		East Junction Buoy		44 37	1132	124 02	296	"	"	"	X			"
		Channel Buoy #12*		44 37	848	124 02	435	"	"	"	X			"
		Channel Buoy #15*		44 36	1391	124 00	1174	"	"	7/14/53	X			"
		Channel Buoy #21*		44 35	718	124 01	255	"	"	"	X			"
		Channel Buoy #23*		44 35	190	124 01	245	"	"	7/24/53	X			"

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

* TABULATE SECONDS AND METERS

~~NON-FLOATING AIDS DISCONTINUED FOR CHARTS~~

TO BE CHARTED } STRIKE OUT ONE
~~TO BE CHARTED~~ Report, Oregon 8 October, 1953

I recommend that the following objects which have ~~(unnecessary)~~ been inspected from seaward to determine their value as landmarks be charted on ~~(unnecessary)~~ the charts indicated.
The positions given have been checked after listing by G. E. Hayden

same as letter 935(1953)

G. E. Hayden

Chief of Party.

STATE	CHARTING NAME	DESCRIPTION	SIGNAL NAME	POSITION		DATUM	METHOD OF LOCATION AND SURVEY NO.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED
				LATITUDE * D. M. METERS	LONGITUDE * D. P. METERS							
		Channel buoy #26*		44 34	124 00	77	1927	62532	7/24/53	X		6098
		Channel buoy #28*		44 34	801	123 58	1595		8/7/53	X		
		Channel buoy #29*		44 34	777	123 58	941			X		
		Channel buoy #34*		44 34	855	123 57	1089			X		
		Channel buoy #36*		44 34	1995	123 57	1073		8/10/53	X		
		Channel buoy #38*		44 35	76	123 57	705			X		
		Channel buoy #39*		44 35	187	123 57	785			X		
		Channel buoy #43*		44 35	404	123 57	44			X		
		Channel buoy #45*		44 35	1300	123 56	255		8/11/53	X		

Show it on Sketch

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and *nonfloating* aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.
* TABULATE SECONDS AND METERS

NONFLOATING AIDS ~~OROKAWA DIVISION OF OREGON HARBORS~~

TO BE CHARTED
~~NONFLOATING AIDS~~

STRIKE OUT ONE

Harport, Oregon

6 October 1953

I recommend that the following objects which have ~~(examined)~~ been inspected from seaward to determine their value as landmarks be charted on ~~(Hydrographic)~~ the charts indicated.

The positions given have been checked after listing by G. J. Bayma

Sanborn 1914-1935 (1953)

G. J. Bayma

Chief of Party.

STATE	CHARTING NAME	DESCRIPTION	SIGNAL NAME	POSITION				DATUM	METHOD OF LOCATION AND SURVEY NO.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED
				LATITUDE*	LONGITUDE*	D.M. METERS	D.P. METERS							
OREGON		OREGON COAST												
		White conical tower	HEAD	44 40	124 04	1139.0	915.6	NA 1927	Triangle-Tallion	1906	X	X		5902 6098
		Harport, Municipal Airport, beacon	BEA	44 35	124 03	368.6	792.2	"	"	1950		X	X	5802 6098
		YACUTIA BAY White square daymark with red vertical stripes on pile structure (H-8039)	FRONT	44 37	124 03	204.7	763.7	"	USED	1953	X			6098
		STRANGE RANGE White diamond daymark with red vertical stripes on skeleton tower (H-8039)	REAR	44 37	124 03	439.6	342.7	"	"	1953	X			6098
		PONT BASIN WEST LIGHT White platform on pile (H-8039)	WEST	44 37	124 02	1472.3	1282.5	"	"	1953	X			6098
		PONT BASIN EAST LIGHT White platform on pile (H-8039)	EAST	44 37	124 02	1323.9	508.7	"	"	1953	X			6098
		LIGHT 10 White platform with red triangle on dolphin (H-8039)	BAY	44 37	124 02	1039.1	1066.1	"	"	1953	X			6098

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

* TABULATE SECONDS AND METERS

NONFLOATING AIDS ~~ORIGINATION AND REVISIONS FOR CHARTS~~

TO BE CHARTED
~~DO NOT CHART~~

STRIKE OUT ONE

Keport, Oregon

6 October 19 38

I recommend that the following objects which have ~~been~~ been inspected from seaward to determine their value as landmarks be charted on (~~charts~~) the charts indicated.
The positions given have been checked after listing by O. J. Boyer

from a little 935 (1953)

O. J. Boyer

Chief of Party.

STATE	OBSCURE	CHARTING NAME	DESCRIPTION	SIGNAL NAME	POSITION			DATUM	METHOD OF LOCATION AND SURVEY NO.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED
					LATITUDE * ° ' "	LONGITUDE * ° ' "	D.M. METERS							
			YACHTING PLY. (Contd.)											
		LIGHT 14	White house with red triangle on delta	JOB	44 36	124 01	1687.1	261.4	MA 1927	1953	X			6098
			YACHTING RIVER											
		LIGHT 17	White square house with black rectangle on opposite parts.	SEVEN	44 36	124 00	733.0	713.3	"	1953	X			6098
		LIGHT 19	White square house with black rectangle	DOM	44 35	124 00	1323.9	864.1	"	1953	X			6098
		LIGHT 20	White square house with red triangle	ZMB	44 35	124 01	851.7	397.4	"	1953	X			6098
		LIGHT 22	White square house with red triangle	YIN	44 35	124 01	107.5	560.1	"	1953	X			6098
		LIGHT 25	White square house with black rectangle	YOG	44 35	124 00	32.8	885.3	"	1953	X			6098
		LIGHT 30	White square house with red triangle	MAI	44 34	123 58	480	570	"	1953	X			6098

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

TO BE CHARTED
~~TO BE CHARTED~~

STRIKE OUT ONE

NONFLOATING AIDS ~~ON THE BANKS OF THE COAST~~

Report, Oregon

6 October, 1953

I recommend that the following objects which have ~~been~~ been inspected from seaward to determine their value as landmarks be charted on ~~(the chart)~~ the charts indicated.

The positions given have been checked after listing by C. J. Byrnes

From and letter 935 (1953)

C. J. Byrnes

Chief of Party.

CHARTING NAME	DESCRIPTION	SIGNAL NAME	POSITION		DATUM	METHOD OF LOCATION AND SURVEY NO.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED	
			LATITUDE *	LONGITUDE *								
			° ' "	° ' "								
LIGHT 32	YAGUINA RIVER (Channel) White square bar with red triangle on white platform on dolphin	RDW	44 34	555	123 57	1238	MA 1927	Radial Plot	1953	X		6098
LIGHT 37	White square house with black rectangle	ROD	44 35	63	123 57	1046	"	"	1953	X		6098
LIGHT 42	White square house with red triangle	ORW	44 35	489.0	123 56	733.7	"	Radial Plot	1953	X		6098
LIGHT 44	White square house with red triangle	PST	44 35	1082	123 56	139	"	Radial Plot	1953	X		6098
LIGHT 47	White cylinder with black rectangle on white platform on dolphin	PLX	44 35	1576	123 56	444	"	"	1953	X		6098

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

* TABULATE SECONDS AND METERS

Name	Latitude			Longitude		D.P. (meters)	Pos No.	Date of Location	Survey No.
	°	'	D.M. (meters)	°	'				
Approach Lighted Whistle Buoy "Y"	44	35	1623	124	06	1010	5a 104	6/12/53	H-8040
Entrance Lighted Bell Buoy "1"	44	36	566	124	05	840	4a 62	6/12/53	"
Entrance Buoy "2"	44	36	761	124	05	214	3a 39	6/12/53	"
Yaquina Reef Buoy "3"	44	36	1151	124	04	1299	2a 33	6/12/53	"
North Jetty Gong Buoy "5"	44	36	1413	124	04	790	6a 28	6/12/53	"
Channel Lighted Buoy "7"	44	37	142	124	03	1410	8a 22	6/3/53	H-8039
West Junction Buoy	44	37	1246	124	03	194	5a 13	6/3/53	"
Channel Buoy "9"	44	37	1212	124	02	958	4a 19	6/3/53	"
Channel Buoy "11"	44	37	1111	124	02	548	2a 12	6/3/53	"
East Junction Buoy	44	37	1132	124	02	296	1a 16	6/3/53	"
Channel Buoy "12"	44	37	848	124	02	435	3a 23	6/3/53	"
Channel Buoy "15"	44	36	1391	124	00	1174	2a 24	7/14/53	H-8041
Channel Buoy "21"	44	35	718	124	01	255	87a 14	7/14/53	"
Channel Buoy "23"	44	35	190	124	01	245	35d 12	7/24/53	"
Channel Buoy "26"	44	34	1487	124	00	77	94e 12	7/28/53	"
Channel Buoy "28"	44	34	801	123	58	1295	6g 10	8/7/53	"
Channel Buoy "29"	44	34	777	123	58	964	7g 9	8/7/53	"
Channel Buoy "34"	44	34	833	123	57	1089	88g 7	8/7/53	"
Channel Buoy "36"	44	34	1595	123	57	1073	28h 9	8/10/53	"
Channel Buoy "38"	44	35	76	123	57	705	24h 10	8/10/53	"
Channel Buoy "39"	44	35	167	123	57	783	25h 6	8/10/53	"
Channel Buoy "41"	44	35	404	123	57	44	62h 10	8/10/53	"
Channel Buoy "45"	44	35	1300	123	56	253	35j 7	8/11/53	"

APPROVAL SHEET

The field work was personally supervised and the boat sheets were inspected daily by the chief of party. The survey is considered complete and adequate. Because of the constant adverse weather on the Oregon coast a complete and thorough development of Yaquina Reef could not be accomplished as desired.

The boat sheets are approved.



C. J. Beyma
CDR., USC&GS
Chief of Party

Yaquina Bay, Oregon.

The smooth sheet was made by hand on Whatman paper. The shoreline is from sheets T 11136, T 11137 & T 9370. Signals are from these sheets and Graphic Control Sheet WCFP-A-53. Lad, a dolphin off the east end of a log boom or jetty, was relocated by using the air photographs. Apparently the end of the jetty was located in the first instance. ~~WCFP-A-53~~ applied to H-8039 and then destroyed.

The field party furnished ten letter size sheets showing sketches of wharves. Dimensions were shown but angles and azimuths were sometimes in doubt. These sketches were reproduced on the smooth sheet on scale of 1/1 000. The topographic sheets and the air photographs were used to aid in orientation. It is believed that they have all the accuracy required for the scale of the charts.

*Filed with
films a
day.*

It is recommended that the central waterfront area of Newport be shown in a box on the chart at a large scale.

*new sheet
6015 (1-20,000)
will cover this
area.*

Depth curves are in agreement with the curves of sheets H 8041 and H 8040 to east and west.

Attention is called to the following soundings near the entrance to the bay.

ϕ	λ	Position	Feet	Remarks.
44° 36.84'	124° 04.23'	42-43g	17	Very close to entrance range.
37.00	03.90	16g	18	30 M. north of range.
36.98	03.95	20-21g	15	40 M. north of range.
36.74	04.28	50-51j	17	The profile shows a slender sharp trace which could be from a log or stump.
36.83	04.28	151-152j	20	60 M. south of range.
			19	On range.

Edgar L. Smith
Edgar L. Smith
Cart. Engr.

DIVISION OF CHARTS
REVIEW SECTION - NAUTICAL CHART BRANCH
REVIEW OF HYDROGRAPHIC SURVEY

REGISTRY NO. H-8039

FIELD NO. WCFP-05153

Oregon, Newport, Yaquina Bay

Project CS-356

Surveyed - April - August, 1953

Scale 1:5,000

Soundings:

Control:

808 Fathometer

Sextant fixes on
shore signals

Chief of Party - C. J. Beyma
Surveyed by - C. J. Beyma and G. E. Haraden
Protracted by - H. C. Parsons
Soundings plotted by - H. C. Parsons
Verified and inked by - J. T. Gallahan and I. M. Zeskind
Reviewed by - I. M. Zeskind 9/1/54
Inspected by - R. H. Carstens

1. Shoreline and Control

The shoreline originates with the reviewed manuscripts of air-photographic surveys T-11136 and T-11137 of 1953, and the unrevised manuscript of air-photographic survey T-9370 (1953).

The source of the control is described in the Descriptive Report.

2. Sounding Line Crossings

Depths at crossings are in adequate agreement.

3. Depth Curves and Bottom Configuration

The usual depth curves are adequately delineated.

The bottom is fairly irregular. It drops sharply off inshore mud flats and shoal areas to the channel deeps. Dredging and current action have left numerous irregularities in the deeper areas.

4. Junctions with Contemporary Surveys

An adequate junction was effected with H-8041 (1953) on the east. The junction with H-8040 (1953) will be considered in the review of that survey.

5. Comparison with Prior Surveys

- A. H-998 (1868-88), 1:10,000
H-1764 (1868), 1:10,000

These early surveys together cover the area of the present survey. A comparison between the prior and present surveys reveals many changes in bottom configuration which are attributed to natural and artificial causes, such as the action of the current on the bottom, the construction of jetties, breakwaters, groins, piers, docks and bulkheads and the reclaiming of land. An example of the change in bottom configuration occurs in the vicinity of lat. $44^{\circ}37.7'$, long. $124^{\circ}02.8'$, where a prior shoal which was approximately one-half mile long and one-tenth of a mile wide and which uncovered 1-3 ft. at MLLW, falls in present depths of 11-24 ft. The shoreline has also changed in a number of places, as for example in the vicinity of lat. $44^{\circ}36.8'$, long. $124^{\circ}03.8'$, where the shoreline has accreted as much as 0.3 mile.

The present survey is adequate to supersede the prior surveys within the common area.

- B. H-3727 (1914), 1:10,000

A comparison between the prior and present surveys reveals many changes in the bottom configuration and the shoreline. These changes are attributed to the natural and artificial causes enumerated in paragraph A above. Examples of changes in bottom configuration occur in lat. $44^{\circ}36.87'$, long. $124^{\circ}04.14'$, where a prior depth of 11 ft. falls in present depths of 23 ft., and in lat. $44^{\circ}37.79'$, long. $124^{\circ}02.60'$, where a prior depth of 13 ft. falls on the present survey in an area which uncovers 1-3 ft. at MLLW. Natural changes in the shoreline are caused principally by accretion to the shoreline, as for example, in lat. $44^{\circ}37.3'$, long. $124^{\circ}02.75'$, where the shoreline has accreted as much as 0.3 mile.

The present survey is adequate to supersede the prior survey within the common area.

6. Comparison with Chart 6058 (latest print date 9/6/54)

A. Hydrography

The charted hydrography within the limits of the dredged channel and adjacent thereto originates with the U. S. Corps of Engineers' surveys of 1954 (Bps 51513 and 51628) which were accomplished subsequent to the present survey. Outside the aforementioned area, the charted hydrography originates with the U. S. Corps of Engineers' survey of 1949 (Bp 45818), supplemented by a few soundings from the present survey. In the latter area only minor differences of 1-2 ft. between the charted and present depths were noted.

The present survey supersedes the charted hydrography which falls outside the limits of the U. S. Corps of Engineers' surveys of 1954.

B. Aids to Navigation

The present survey positions of aids to navigation are in substantial agreement with the charted positions and adequately mark the features intended, except that Buoy C-9, which is charted in lat. $44^{\circ}37.64'$, long. $124^{\circ}02.81'$, in accordance with H O N to M 38, 1951, is located 200 meters to the eastward on the present survey. The charted location more adequately marks the northern limits of the channel.

C. Controlling Depths

The controlling depths in the dredged channel originate with the U. S. Corps of Engineers' survey of 1954 (Bp 51628), which was accomplished subsequent to the present survey.

7. Condition of Survey

- a. The sounding records and Descriptive Report are complete and comprehensive.
- b. The smooth plotting was accurately done.

8. Compliance with Project Instructions

The survey adequately complies with the Project Instructions.

9. Additional Field Work Recommended

This is an excellent basic survey and no additional field work is recommended. As mentioned in paragraph 6B above, the present survey has been superseded in part by the U. S. Corps of Engineers' survey of 1954.


Examined and approved:




H. R. Edmonston
Chief, Nautical Chart Branch



E. R. McCarthy
Acting Chief, Division of Charts



G. R. Fish
Chief, Hydrography Branch



Earl O. Heaton
Chief, Division of Coastal Surveys

GEOGRAPHIC NAMES

Survey No. H-8039

Name on Survey	A On Chart No.	B On previous survey No.	C On U. S. quadrangle Maps	D From local information	E On local Maps	F P. O. Guide or Map	G Rand McNally Atlas	H U. S. Light List	K
<u>Oregon</u>			(for title)					B.G.N.	1
<u>Yaquina River</u>			(" ")						2
<u>Pacific Ocean</u>									3
<u>Newport</u>									4
<u>Yaquina Bay</u>								B.G.N.	5
<u>Southbeach</u>									6
<u>McKeen Point</u>									7
									8
									9
									10
									11
									12
									13
									14
									15
									16
									17
									18
									19
									20
									21
									22
									23
									24
									25
									26
									27

Names approved 5-25-54
L. Heck

Hydrographic Surveys (Chart Division)

HYDROGRAPHIC SURVEY NO. H-8039..

Records accompanying survey:

Boat sheets ..1.; sounding vols. 9.....; wire drag vols.; bomb vols.; graphic recorder rolls; special reports, etc. 1. Smooth Sheet; 1. Descriptive Report;.....

The following statistics will be submitted with the cartographer's report on the sheet:

Number of positions on sheet		1255
Number of positions checked		⊕ 391 ²⁸⁴⁺¹⁰⁺⁹⁷
Number of positions revised		..8..
Number of soundings revised (refers to depth only)		..33
Number of soundings erroneously spaced		..25
Number of signals erroneously plotted or transferred		..0..
Topographic details	Time	..50
Junctions	Time	..15
Verification of soundings from graphic record	Time	..40
Partial Verification -- C.R. Helmer	40 hrs.	5/27/54 - 4/3/54
Partial Verification -- I.M. Leskind	31 hrs	8/23/54
Verification by J.T. Gallahan.....	Total time	237.... Date
	Total	308
Reviewed by <i>I.M. Leskind</i>	Time	45.... Date 9-1-54

⊕ includes 282 Det. Positions #

BHC

TIDE NOTE FOR HYDROGRAPHIC SHEET

~~DIVISION OF COAST AND GEODETIC SURVEY~~

24 May 1954

Division of Charts: R. H. Carstens

Plane of reference approved in
9 volumes of sounding records for

HYDROGRAPHIC SHEET 8039

Locality Yaquina River, Oregon

Chief of Party: C. J. Beyma in 1953

Plane of reference is mean lower low water, reading
3.2 ft. on tide staff at Newport
17.2 ft. below B. M. 5 (1933)

Height of mean high water above plane of reference is 7.3 feet.

Condition of records satisfactory except as noted below:

E. C. McKay
Tides Branch

Chief, Division of Tides and Currents.




Chart 5802

NAUTICAL CHARTS BRANCH

SURVEY NO. H-8039

Record of Application to Charts

DATE	CHART	CARTOGRAPHER	REMARKS
	6058	ESY	Partially app. Before After Verification and Review
Nov '54	6055	H. E. Mac Ewen	Before After Verification and Review J. M. G.
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review
			Before After Verification and Review

M-2168-1

A basic hydrographic or topographic survey supersedes all information of like nature on the uncorrected chart. Give reasons for deviations, if any, from recommendations made under "Comparison with Charts" in the Review.