

8040

Diag. Cht. Nos. 5802 & 5902-2

Form 504

U. S. COAST AND GEODETIC SURVEY

DEPARTMENT OF COMMERCE

DESCRIPTIVE REPORT

Type of Survey HYDROGRAPHIC

Field No. WCFP-1153 Office No. H-8040

LOCALITY

State OREGON

General locality NEWPORT

Locality APPROACHES TO YAQUINA RIVER

194 53

CHIEF OF PARTY

C. J. Beyma

LIBRARY & ARCHIVES

DATE

B-1870-1 (1)

8040

DEPARTMENT OF COMMERCE
U. S. COAST AND GEODETIC SURVEY

HYDROGRAPHIC TITLE SHEET

The Hydrographic Sheet should be accompanied by this form, filled in as completely as possible, when the sheet is forwarded to the Office.

REGISTER No. H 8040

Field No. WCFP 1153

State Oregon

General locality Newport

Locality Approaches to Yaquina River

Scale 1/ 10 000 Date of survey 12 June * 8 September 1953

Instructions dated 2 March 1953

Vessel Launch CS 160

Chief of party C.J. Beyma

Surveyed by C.J. Beyma & G.E. Haraden

Soundings taken by ~~Fathometer~~ graphic recorder, hand lead, wire

Fathograms scaled by Party personnel

Fathograms checked by C.J. Beyma & G.E. Haraden

Protracted by C.R. Lehman

Soundings penciled by C.R. Lehman

Soundings in ~~Fathoms~~ feet at ~~MLLW~~ and are true depths

REMARKS: Plotted in Seattle Processing Office.

DESCRIPTIVE REPORT TO ACCOMPANY HYDROGRAPHIC SURVEY

H-8039 (1953)
H-8040 (1953)
H-8041 (1953)

Field Sheet (WCFP 05153)
Field Sheet (WCFP 1153)
Field Sheet (WCFP 1253)

YAQUINA BAY OREGON AND APPROACHES

Project CS-356
West Coast Field Party
Surveyed by C. J. Beyma, G. E. Haraden

Season of 1953
C. J. Beyma, Chief of Party

A. PROJECT

The work was done in accordance with instructions for project CS-356 dated 2 March 1953.

B. SURVEY LIMITS AND DATES

The limits of this survey include Yaquina River and Approaches and extend from latitude $44^{\circ} 34.0'$ to latitude $44^{\circ} 41.0'$ and from longitude $123^{\circ} 55.6'$ to longitude $124^{\circ} 07.0'$.
 $4^{\circ} 03.7'$

Field work was begun 1 April 1953 and was completed 16 October 1953. Work in Yaquina Bay and River progressed satisfactorily, however considerable trouble was encountered in the adjacent offshore area. Progress was retarded by unfavorable weather and the fact that the launch used was unsuitable for sounding on the unprotected coast. Sounding on the reef immediately north of the jetties was unsafe because of the presence of continuous breakers during the working season.

C. VESSEL AND EQUIPMENT

The hydrography was performed exclusively with launch CS-160 which operated from a shore base at Newport, Oregon. The turning radius of the launch was approximately 30 meters. Fathometers of the 808 type were used. Fathometer number 152SPX was used at all times except when inoperative, in which case number 154SPX was substituted until repairs could be made.

D. TIDE AND CURRENT STATIONS

Two portable recording tide gages and one tide staff were used in connection with this survey. A tide gage at the U. S. Coast Guard Station in Newport was maintained throughout the entire working season for reducing soundings obtained on sheets H-8039 and H-8040. A tide gage at Yaquina was also maintained throughout the entire working season and was used for reducing soundings on that portion of Sheet H-8041 which is west of longitude $123^{\circ} 58'$. For the remainder of Sheet H-8041 a tide staff at Toledo, Oregon was used.

D. TIDE AND CURRENT STATIONS, CONTD.

Five current stations were occupied as follows:

- (1) On the north side of the channel under the highway bridge between Newport and South Beach, observations for 100 hours.
- (2) Near the docks at Newport near the West Junction Buoy, observations for 100 hours.
- (3) Off Yaquina, observations for 97 hours.
- (4) Between the jetties near the entrance to Yaquina Bay, observations for 9 1/2 hours.
- (5) Three tenths miles north of Light 47, Yaquina River, observations for 29 hours.

H-8039

E. SMOOTH SHEETS

Smooth sheets for this survey ^{were} ~~are to be~~ drawn and completed by the Seattle Processing Office.

F. CONTROL STATIONS

Positions of hydrographic signals and triangulation stations used for the control of this survey were furnished by the Portland Photogrammetric Office. Photo-hydro signals were transferred to the boat sheets by pricking through photographic manuscripts T-11136, T-11137 and ~~T-11138~~. Refer to Descriptive Report, Project Ph-113 for further details regarding control for this survey.

Seven hydrographic signals were located by planetable methods. Refer to Descriptive Report covering Topographic sheet WCFP-A-53.

Hydrographic signals ROC and POLE were located by four sextant cuts from the launch at various positions south of Yaquina Head. These cuts are recorded in Volume II pages 29 and 30, H-8040.

Hydrographic signals HEX and KEY were located by measuring along the Boat Basin breakwater from the Boat Basin Lights. These distances are recorded in Volume I page 3, H-8039.

H-8039

No difficulty was encountered with any of the control signals.

G. SHORLINE AND TOPOGRAPHY

All shoreline for this survey was furnished by the Portland Photogrammetric Office and transferred to the boat sheets from Manuscripts T-11136, T-11137 and ~~T-11138~~; by the West Coast Field Party.

G. SHORELINE AND TOPOGRAPHY CONTD.

The low water line in Yaquina Bay and Yaquina River is adequately defined. On the outside coast it was impossible to delineate the low water line because of alongshore breakers. H-8039 & H-8041
H-8040

H. SOUNDINGS

Fathometer 152SPX and 154SPX when received from the Washington office were equipped with 820 fms/sec. tachometers. 800 fms/sec. tachometers were requisitioned from Washington early in May but were received by the party late in June. The 820 fms/sec. tachometers were used in fathometers 152SPX and 154SPX on boat sheet H-8039 from 3 June 1953 thru 10 June 1953 day letters a, b, c, d, e, and f. On boat sheet H-8040 the 820 fms/sec. tachometer was used on 12 June 1953 day letter a. On subsequent days 800 fms/sec. tachometers were used on boat sheets H-8039, H-8040 and H-8041.

The fish on the keel of the launch was used on boat sheet H-8039 letter days a thru g and on boat sheet H-8040 on letter days a and b. On June 26, 1953 an outboard fish was installed on the launch. The reason being that the fish attached to the keel gave unsatisfactory results especially when sounding on the outside coast. The launch has a ramp bow, because of its design when sounding on the coast, the launch would ride over every swell causing air to pass under the keel resulting in large void sections on the fathograms. To rectify this an outboard fish was installed on the starboard quarter of the launch to enable this party to sound at a greater speed and thus take advantage of favorable weather on the open coast. Because of the construction of the launch the conventional type bar could not be used advantageously, so a fathometer receiver was used in taking bar checks. By lowering the receiver unit directly under the outboard fish attached to a graduated wire rope, a value of 1.0 feet was found to give good results when taking a bar check. This value was then doubled and adopted as initial setting, thus eliminating any index correction while sounding.

After sounding for two days on Sheet H-8040 b and c days, and h day on Sheet H-8039 it was discovered by using 2.0 as an initial setting the fish would ground before the launch and a reading of less than three feet recorded on the fathogram. The bottom of the housing enclosing the fathometer units was measured with a steel tape to be 38 inches below the surface of the water. A bar check was taken with a conventional metal bar suspended below the fish and the bar check corroborated that initial setting should have been 3.2 feet in lieu of 2.0 feet as recorded on the fathograms for h day on sheet H-8039 and c and d days on Sheet H-8040. Handlead soundings were taken against fathometer soundings also pole soundings against fathometer soundings all indicating the initial to be 3.2 feet. So an index correction of +1.2 feet was applied to the soundings obtained on those days. Why the unit gave erroneous bar checks yet consistent thru the range of depths of the A Scale cannot be accounted for unless for the reason that the unit was kept out of the water and not soaked well enough to give the correct results.

H. SOUNDINGS CONTD.*1 day on H-8040 (July 7)*

Since the outboard fish grounded before anything else it was advisable to raise it to a point which was less than the draft of the launch. On 6 July the fish was raised to 27 inches below the water surface. Subsequent bar checks indicated the new initial to be 2.2 feet. Both type bar checks that is the metal bar, and the receiver unit gave the same results. After h day Sheet H-8039 the receiver unit used in taking bar checks was submerged in a large can of sea water at all times, to allow the unit to become well soaked.

On Sheet H-8040 it was impossible to obtain satisfactory bar checks with an ordinary metal bar. The sea action and under water currents would cause the bar to move in every direction except under the fish. The receiver unit was used successfully on the A Scale only. When switching to the B Scale the fathogram consistently indicated a shoaler depth of 2 feet throughout the B Scale range. On the C Scale range there was no correction. The fathogram and the measured depth on the receiver unit agreed; likewise on the D Scale. By anchoring the launch in the Bay in a depth of about 40 feet the A Scale and B Scale agreed, so no phase correction was applied to the soundings on the B Scale. To determine the phase correction on the C and D Scales the launch was allowed to drift and comparative readings were taken on the B and C Scales and similary on the C to D Scales. On the C Scale the correction was -1.2 feet and D Scale -2.6 feet. These corrections were obtained by scanning the peaks and troughs on either scales and obtainning a mean. It was accepted for about 75% of the survey that the bar checks on the various fathometer scales were correct by using the fathometer receiver unit as a bar until it was decided to actually check the scales by bottom comparison. It was discovered that the receiver unit was registering erroneously on the B, C and D Scales in comparison with the depth of the bottom recorded on the fathograms on the various scales. Attempts were made to check the bottom comparison with a leadline. Because of the sea and wind conditions the leadline could not be read accurately. It was impossible to obtain a vertical depth with the leadline or to accurately average the height of the swells. The leadline would be either leading aft or inboard or outboard. To record such a reading would only introduce additional errors.

Weather conditions on the outside coast were far from ever being calm. Even what was considered calm to accomplish launch hydrography, the seas were 4 to 6 feet high. By inspecting the fathograms it can be clearly seen the conditions of the seas while sounding on the outside coast. On many days the fathograms cannot be scanned to average the correct depth within 2 feet. It seems impracticable to make any corrections to the soundings except for tide because of the prevailing weather conditions this season along the Oregon Coast.

Temperature and salinity observations were not observed principally because every workable day on the coast was utilized in launch hydrography. During the entire season there were so few days that a launch could actually work on the coast. Even these days were rough, far from what one would consider calm or ideal for launch hydrography.

I. CONTROL OF HYDROGRAPHY

Sextant fixes, using the three point method, were used for horizontal control of the survey, except for sounding lines in the sloughs at Oysterville. Lines run in these sloughs were midchannel lines and only the times when abeam signals and times of all turns were recorded for control data. Sextant fixes were not taken because sufficient signals were not visible when needed and the angles changed too rapidly when they were visible. In the western slough at Oysterville the boat sheet soundings were plotted by dead reckoning.

"F" DAY

Soundings from position 89 - 90A of H-8039 were rejected because of a 13 foot sounding which plotted out of place. The area was thoroughly developed on an overlay, on 21 August 1953, q day, and the 13 foot sounding was not found.

H-8039,
H-8040,
& H-8041

J. ADEQUACY OF SURVEY

Survey Sheets H-8039 Yaquina Bay, and H-8040 Yaquina River, are adequate and complete and should supersede prior surveys for charting. Boat Sheet H-8040 is adequate for navigation purposes, however, due to the prevailing heavy seas and strong NW'ly winds, the offlying reef could not be thoroughly developed. Shoal soundings from prior surveys should be retained for charting.

H-8040,
H-8039 &
H-8041

Junctions with prior surveys H-4894 (1928) and H-4749 (1927) were made on the west and north with considerable overlap and depth curves can be adequately drawn. *Sec P 5 of Review*

K. CROSSLINES

A total of 7.6% crosslines were run on Sheet H-8041 Yaquina River N-8041 with very good agreement.

Crosslines to the extent of 7.4% were run on Sheet H-8039 Yaquina Bay, with generally good agreement except for crossings between the jetties. The system of short lines between the jetties and normal to the channel should be adjusted when smooth plotted allowing for the launch to attain sounding speed and spacing the soundings accordingly.

H-8039

On Sheet H-8040 7.6% of the total mileage was crosslines. All crossings were in good agreement.

L. COMPARISON WITH PRIOR SURVEYS

H-8041

There are no recent prior surveys of Yaquina River, However comparison with Sheet H-3728, 1914 scale 1:10,000 indicates that the river has shoaled from zero to three feet between Mc Lean Point and Toledo.

H-8041

(5)
L. COMPARISON WITH PRIOR SURVEYS CONTD

H-8039

Survey H-3727, 1914 scale 1:10,000 is obsolete and the only recent survey of this area is a condition survey by the U. S. Corps of Engineers. Engineers survey Sheet YB-1-249, scale 1:5,000 May 1953 agrees with soundings of this survey in the channel.

H-8039

H-8040

Comparison with old survey H-4894, 1928, scale 1:40,000 is in good agreement at the junctions.

Survey H-4749, 1927, scale 1:20,000 is in good agreement, however shoaler depths were found on the reef west of and southwest of Yaquina Head.

Comparison with old survey H-4879, 1928, scale 1:20,000 is generally good except over the reefs. Shoaler soundings were obtained on the south reef and this reef was found to extend to the southern limits of the survey. The shoal soundings on the north reef north of Yaquina Reef Buoy 3 could not be verified because of breakers in that area.

M. COMPARISON WITH CHART

Comparison with Chart 6058, August 1942 (19th Edition), scale 1:20,000, reveals the following:

The area southwest of Boat Basin West Light has shoaled considerably as a result of the Engineers emptying their dredgings on the south side of the breakwater and the subsequent shifting in a westerly direction.

H-8039
1953

The channel under the highway bridge has ^{scoured} shoaled up to five feet deeper than the depths on the published chart.

The shallow channel southeast of McLean Point no longer exists. Construction is under way in that area at present.

H-8041
1953

The slough at Oysterville extends south of the limits of Chart 6058 and is navigable by small boats. Lumber tugs haul log rafts through this slough to the mills along the Yaquina River. For this reason it is recommended that the limits of Chart 6058 be extended to include this slough.

H-8044

^{on Chart 5802 (8-9-54)}
No indication of the sunken wrecks in latitude $44^{\circ} 36'$ Longitude $124^{\circ} 06'$ and Latitude $44^{\circ} 37'$ Longitude $124^{\circ} 06'$ was found during this survey. ^{Deleted from chart}
^{ent survey in wk. locations 70-80 ft.)} ^{37.22'} ^{04.78'} ^{depths on pres.}

The sunken wreck charted at Latitude $44^{\circ} 36' 58''$ Longitude $124^{\circ} 05' 12''$ should be charted as stranded wreck bearing 5.2 feet at MLLW, see position data, Volume I, page 4, H-8040.

M. COMPARISON WITH CHART CONTD

Ch 6058 (6-18-51) 57'
The four foot rock charted at latitude $44^{\circ} 37.6'$ longitude $124^{\circ} 04.25'$ is misplaced. This survey indicated a shoal approximately 220 meters NNE of the charted position, see boat sheet H-8040.

Retain as charted. (see TP 6 of Review)

Charted on 6058 (6/18/51) South
Verification of the three foot rock, south of the jetties was not possible and therefore should be retained on the chart.

Retain on Chart. (see TP 6 of Review)

Investigations of the charted shoal at latitude $44^{\circ} 39.88'$ longitude $124^{\circ} 05.03'$ indicates that the symbol as charted should be deleted. This shoal is a continuation of Yaquina Reef which runs from the entrance channel north to the limits of the survey.

Delete. see TP 5 of Review

The offshore reef on chart 6058 is so extensive that the many shoal soundings charted could well exist although all were not verified during this survey. It is therefore recommended that the shoal soundings from prior surveys be retained for charting.

see TP 6 of Review

The rocks west of Coquille Point and at latitude $44^{\circ} 36.7'$ longitude $124^{\circ} 00.7'$ were found as charted.

H-8041

The rock charted at latitude $44^{\circ} 35.00'$ longitude $124^{\circ} 00.32'$ should be shown as rocks awash baring 3.4 feet at MLLW.

No indications of the following charted features were found during the survey and they should be deleted from the chart:

Charted Feature

Latitude

Longitude

Rock Symbol

 $44^{\circ} 39.88'$ $124^{\circ} 05.03'$

Chimney

 $44^{\circ} 34.7'$ $124^{\circ} 00.2'$

Dolphin

 $44^{\circ} 37.31'$ $124^{\circ} 02.0'$

Rock

 $44^{\circ} 37.31'$ $124^{\circ} 02.05'$

14 ft. Sdg. (from H-998 (1868))

 $44^{\circ} 38.90'$ $124^{\circ} 04.15'$

2 ft. Rock

 $44^{\circ} 36.6'$ $124^{\circ} 04.42'$

(see 3rd TP above)

H-8039

*Carried forward to H-8040
Retain on Chart.
(see TP 6 of Review)*

N. DANGERS AND SHOALS

Newly found dangers within the limits of this survey include the following:

Sheet No.	Danger	Latitude	Longitude	Least Depth	Position No.
H-8040	Stranded Wreck	$44^{\circ} 37.32'$	$124^{\circ} 04.78'$	Bares 5.1 ft. @ MLLW	1 a
H-8041	Steel Boiler	$44^{\circ} 36.81'$	$124^{\circ} 01.11'$	Bares 3.8 ft @ MLLW	1 a
H-8041	Log	$44^{\circ} 34.47'$	$123^{\circ} 59.47'$	Bares 6.0 ft @ MLLW	6 q
H-8041	3 Logs	$44^{\circ} 34.34'$	$123^{\circ} 58.97'$	One End Floats	23, 24 & 25 g

H-8041

N. DANGERS AND SHOALS CONTD

Sheet No.	Danger	Latitude	Longitude	Least Depth	Position No.
H-8041	Log	44° 34.38'	123° 58.18'	One End Floats	67 g
H-8041	Log	44° 35.07'	123° 57.63'	" " "	26 h
H-8041	Log	44° 35.10'	123° 57.56'	" " "	27 h
H-8041	Log	44° 35.53'	123° 56.30'	" " "	63 j
H-8041	Stump	44° 36.71'	124° 01.44'	Bares 9.0 ft. @ MLLW	69 c

H-8041

O. COAST PILOT INFORMATION

The following are corrections to Coast Pilot Notes for Yaquina Bay, Oregon Chart No. 6058. Page and line numbers refer to publication "United States Coast Pilot Pacific Coast Seventh (1951) Edition";

Page 326 Line 41; States "26 feet deep over the bar." The present survey indicates 22 feet least depth over the bar.

H-8040

Page 327 Line 34; Strike out lines 34, 35 and 36. Insert - The controlling depth in Yaquina River to Toledo in August 1953 was 9 feet; In Depoe Creek the controlling depth was 3 feet in August 1953.

H-8039
(1953)

Page 328 Line 17; Strike out "The wharves have 10 to 12 feet alongside. Insert - The wharves have 5 to 6 feet alongside.

H-8041
(1953)P. GEOGRAPHIC NAMES

All geographic names within the limits of this survey were investigated by the Portland Photogrammetric Party and a special report was submitted by that office.

Submitted By

C. J. Beyma
CDR., USC&GS

Approved & Forwarded

C. J. Beyma
CDR., USC&GS
Chief of Party

8039
8040
8041

TIDE NOTE

Sheet H-8039

Field Sheet WCFP 05153

An automatic recording portable tide gage at latitude $44^{\circ} 37.55'$ longitude $124^{\circ} 03.30'$ was used to reduce the soundings for survey H-8039. Mean lower low water on the staff corresponds to a reading of 3.2 feet.

No corrections to the observed readings were applied for differences in time or height.

Sheet H-8040

Field Sheet WCFP 1153

The same tide gage at latitude $44^{\circ} 37.55'$ longitude $124^{\circ} 03.30'$ was used for the reduction of soundings on survey H-8040 as was used for H-8039. No corrections were applied for differences in time or height. ✓

Sheet H-8041

Field Sheet WCFP 1253

Two tide stations were used for reducing the soundings for survey H-8041. A portable recording gage at latitude $44^{\circ} 36.17'$ longitude $124^{\circ} 00.57'$ was used for reducing all soundings on survey H-8041 west of longitude $123^{\circ} 58.00'$. Mean lower low water on the staff corresponds to a reading of 1.9 feet.

A tide staff at latitude $44^{\circ} 37.04'$ longitude $123^{\circ} 56.16'$ was used for reducing all soundings on this survey east of longitude $123^{\circ} 58.00'$. Mean lower low water on the staff corresponds to a reading of 3.4 feet.


No corrections for differences in time or height were applied to either the gage or the staff readings.

Name	Latitude			Longitude			D.P. (meters)	Pos No.	Date of Location	Survey No.
	°	'	D.M. (meters)	°	'					
Approach Lighted Whistle Buoy "Y" ✓	44	35	1623	124	06	1010	5a	104	6/12/53	H-8040
Entrance Lighted Bell Buoy "1" ✓	44	36	566	124	05	840	4a	62	6/12/53	"
Entrance Buoy "2" ✓	44	36	761	124	05	214	3a	39	6/12/53	"
Yaquina Reef Buoy "3"	44	36	1151	124	04	1299	2a	33	6/12/53	"
North Jetty Gong Buoy "5" ✓	44	36	1413	124	04	790	6a	28	6/12/53	"
Channel Lighted Buoy "7"	44	37	142	124	03	1410	8a	22	6/3/53	H-8039
West Junction Buoy	44	37	1246	124	03	194	5a	13	6/3/53	"
Channel Buoy "9"	44	37	1212	124	02	958	4a	19	6/3/53	"
Channel Buoy "11"	44	37	1111	124	02	548	2a	12	6/3/53	"
East Junction Buoy	44	37	1132	124	02	296	1a	16	6/3/53	"
Channel Buoy "12"	44	37	848	124	02	435	3a	23	6/3/53	"
Channel Buoy "15"	44	36	1391	124	00	1174	2a	24	7/14/53	H-8041
Channel Buoy "21"	44	35	718	124	01	255	87a	14	7/14/53	"
Channel Buoy "23"	44	35	190	124	01	245	35d	12	7/24/53	"
Channel Buoy "26"	44	34	1487	124	00	77	94a	12	7/28/53	"
Channel Buoy "28"	44	34	801	123	58	1295	6g	10	8/7/53	"
Channel Buoy "29"	44	34	777	123	58	964	7g	9	8/7/53	"
Channel Buoy "34"	44	34	833	123	57	1089	88g	7	8/7/53	"
Channel Buoy "36"	44	34	1595	123	57	1073	28h	9	8/10/53	"
Channel Buoy "38"	44	35	76	123	57	705	24h	10	8/10/53	"
Channel Buoy "39"	44	35	167	123	57	783	25h	6	8/10/53	"
Channel Buoy "41"	44	35	404	123	57	44	62h	10	8/10/53	"
Channel Buoy "45"	44	35	1300	123	56	253	35j	7	8/11/53	"

APPROVAL SHEET

The field work was personally supervised and the boat sheets were inspected daily by the chief of party. The survey is considered complete and adequate. Because of the constant adverse weather on the Oregon coast a complete and thorough development of Yaquina Reef could not be accomplished as desired.

The boat sheets are approved.


C. J. Beyma
CDR., USC&GS
Chief of Party

~~NONFLOATING AIDS OR~~ LANDMARKS FOR CHARTS

TO BE CHARTED

STRIKE OUT ONE

~~TO BE DELETED~~

Newport, Oregon

6 October 1953

I recommend that the following objects which have ~~(have not)~~ been inspected from seaward to determine their value as landmarks be charted on ~~(deleted from)~~ the charts indicated.

The positions given have been checked after listing by C. J. Beyma

*aids in this list same as
L. 935/1953*

C. J. Beyma

Chief of Party.

STATE OREGON			POSITION				METHOD OF LOCATION AND SURVEY No.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED	
CHARTING NAME	DESCRIPTION	SIGNAL NAME	LATITUDE *		LONGITUDE *								DATUM
			° ' "	D.M. METERS	° ' "	D.P. METERS							
RADIO MAST (WASTERLY OF TWO)	Newport Radio Station (KNPT Tower) ✓ (This is the W l/y of two towers)	STAT	44 39	170.3	124 03	29.6	NA 1927	Triangu-lation	1950	X	X	5902 6058 ✓ 6055 ✓	
LIGHT HOUSE	Abandoned (Yaquina Lighthouse, old)	HOUSE	44 37	850.9	124 03	936.3	"	"	1908	X	X	5802 5902 6058 6055 ✓	
LOOKOUT TOWER	House 9' x 9', 7'4" high on 49' skeleton steel tower *This position was obtained from Corps of Engineers	LOOK	44 37	849.5	124 03	921.9	"	"	"	X	X	5802 5902 6058 6055 ✓	
MARKER (FLR LT)	Newport, Center of Bridge, light	LIGHT	44 37	702.1	124.03	470.0	"	"	1950	X	X	5802 5902 6058 6055 ✓	
TANK	Silver, low elevated with conical Top	RUM	44 37	23	123 56	1031	"	Radial Plot	1953	X		6058 6055 ✓	
STACK (NORTHEAST OF TWO)	Black metal	TAN	44 37	11	123 56	541	"	"	1953	X		6058 6055 ✓	
TANK (ELEVATED)	Black, on steel skeleton	TAP	44 37	0	123 56	440	"	"	1953	X		6055 ✓ 6058	

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

* TABULATE SECONDS AND METERS

DEPARTMENT OF COMMERCE
U. S. COAST AND GEODETIC SURVEY

Sheet 1 of 2

~~NON~~FLOATING AIDS ~~ON LAND~~ FOR CHARTS

TO BE CHARTED
TO ~~BE CHARTED~~

STRIKE OUT ONE

Newport, Oregon

8 October 19 53

I recommend that the following objects which have ~~(nonfloating)~~ been inspected from seaward to determine their value as landmarks be charted on ~~(charts)~~ the charts indicated.

The positions given have been checked after listing by G. E. Haraden

Scale 1022.3
on H-8040

G. J. Bayne

Chief of Party.

STATE			POSITION				DATUM	METHOD OF LOCATION AND SURVEY No.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED
CHARTING NAME	DESCRIPTION	SIGNAL NAME	LATITUDE*		LONGITUDE*								
			° ' "	D.M. METERS	° ' "	D.P. METERS							
	Approach Lighted Whistle Buoy "Y"	↑	44 35	1623	124 06	1010	NA 1927	Hydro CS-356	6/12/53		X	X	* 6055 ✓ 6052 6058
	Entrance Lighted Bell Buoy "1"	↓	44 36	566	124 05	840	"	"	"		X	X	6055 ✓ 6058 6052
	Entrance Buoy "2"		44 36	761	124 05	214	"	"	"	X			6055 ✓ 6058
	Yaquina Reef Buoy "3"		44 36	1151	124 04	1299	"	"	"	X			6055 ✓ 6058
	North Jetty Gong Buoy "5"	↓	44 36	1413	124 04	790	"	"	"	X			6055 ✓ 6058
	Channel Lighted Buoy "7"		44 37	142	124 03	1410	"	"	6/5/53	X			6055 ✓ 6058
	West Junction Buoy		44 37	1246	124 03	194	"	"	"	X			6055 ✓ 6058
	Channel Buoy "9"		44 37	1212	124 02	958	"	"	"	X			6055 ✓ 6058
	Channel Buoy "11"		44 37	1111	124 02	548	"	"	"	X			6055 ✓ 6058
	East Junction Buoy		44 37	1132	124 02	296	"	"	"	X			6055 ✓ 6058
	Channel Buoy "12"		44 37	848	124 02	435	"	"	"	X			6055 ✓ 6058
	Channel Buoy "15"		44 36	1391	124 00	1174	"	"	7/14/53	X			6055 ✓ 6058
	Channel Buoy "21"		44 35	718	124 01	255	"	"	"	X			6055 ✓ 6058
	Channel Buoy "23"		44 35	190	124 01	245	"	"	7/24/53	X			6055 ✓ 6058

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

~~NON~~FLOATING AIDS ~~DECEASE~~ FOR CHARTS

TO BE CHARTED
TO ~~SECRET~~

STRIKE OUT ONE

Newport, Oregon

8 October 1953

I recommend that the following objects which have ~~(removed)~~ been inspected from seaward to determine their value as landmarks be charted on ~~(removed from)~~ the charts indicated.

The positions given have been checked after listing by G. E. Harnden

C. J. Boyne

Chief of Party.

[illegible]

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and *nonfloating aids* to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

* TABULATE SECONDS AND METERS

M-2836-3

DEPARTMENT OF COMMERCE
U. S. COAST AND GEODETIC SURVEY

~~TOP SECRET~~
TO BE DELETED

STRIKE OUT ONE

LANDMARKS FOR CHARTS

Newport, Oregon

6 October 1953

BE DELETED

I recommend that the following objects which have ~~(these)~~ been inspected from seaward to determine their value as landmarks be ~~deleted from~~ (deleted from) the charts indicated.

The positions given have been checked after listing by G. E. Haraden

C. J. Beyma

Chief of Party.

[illegible]

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and *nonfloating aids* to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

DEPARTMENT OF COMMERCE
U. S. COAST AND GEODETIC SURVEY

Sheet 1 of

NONFLOATING AIDS ~~TO BE CHARTED~~

TO BE CHARTED

STRIKE OUT ONE

Newport, Oregon

6 October 1953

I recommend that the following objects which have ~~been~~ been inspected from seaward to determine their value as landmarks be charted on ~~(struck from)~~ the charts indicated.

The positions given have been checked after listing by C. J. Beyna

C. J. Beyna

Chief of Party.

STATE <u>OREGON</u>			POSITION						C. J. Beyna		Chief of Party.		
CHARTING NAME	DESCRIPTION	SIGNAL NAME	LATITUDE *		LONGITUDE *		DATUM	METHOD OF LOCATION AND SURVEY NO.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED
			° ' "	D.M. METERS	° ' "	D.P. METERS							
<u>OREGON COAST</u>													
<u>YACUINA HEAD LIGHTHOUSE</u>	White conical tower	HEAD	44 40	1139.0	124 04	915.6	NA 1927	Triangulation	1908	X	X		5902 6058
deleted on list per 1 of 6-5-8 ok AERO BN.	Newport, Municipal Airport, beacon	BEA	44 35	368.6	124 03	792.2	"	"	1950	X	X		5802 6058
<u>YACUINA BAY</u>													
<u>ENTRANCE RANGE FRONT LIGHT 8</u>	White square daymark with red vertical stripe on pile structure	FRONT	44 37	204.7	124 03	763.7	"	USED	1953	X			6055 6058
<u>ENTRANCE RANGE REAR LIGHT</u>	White diamond daymark with red vertical stripe on skeleton tower	REAR	44 37	439.6	124 03	342.7	"	"	1953	X			6055 6058
<u>BOAT BASIN WEST LIGHT</u>	White platform on pile	WEST	44 37	1472.3	124 02	1282.5	"	"	1953	X			6055 6058
<u>BOAT BASIN EAST LIGHT</u>	White platform on pile	EAST	44 37	1323.9	124 02	508.7	"	"	1953	X			6055 6058
<u>LIGHT 10</u>	White platform with red triangle on dolphin	RAY	44 37	1039.1	124.02	1066.1	"	"	1953	X			6055 6058

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and nonfloating aids to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

* TABULATE SECONDS AND METERS

DEPARTMENT OF COMMERCE
U. S. COAST AND GEODETIC SURVEY

Sheet 2 of 3

NONFLOATING AIDS ~~OR LANDMARKS FOR CHARTS~~

TO BE CHARTED

STRIKE OUT ONE

Newport, Oregon

6 October 1945

I recommend that the following objects which have ~~(be examined)~~ been inspected from seaward to determine their value as landmarks be charted on ~~(charts to be)~~ the charts indicated.

The positions given have been checked after listing by C. J. Boyne

C. J. Boyne

Chief of Party.

STATE <u>OREGON</u>			POSITION						METHOD OF LOCATION AND SURVEY No.	DATE OF LOCATION	HARBOR CHART	INSHORE CHART	OFFSHORE CHART	CHARTS AFFECTED
CHARTING NAME	DESCRIPTION	SIGNAL NAME	LATITUDE *		LONGITUDE *		DATUM							
			° /	" D.M. METERS	° /	" D.P. METERS								
	<u>YACUINA BAY (Contd.)</u>													
LIGHT 14	White house with red triangle on dolphin	JUG	44 36	1687.1	124 01	281.4	NA 1927	Triangulation Ph-113	1953	I				6055 ✓ 6058
	<u>YACUINA RIVER</u>													
LIGHT 17	White square house with black rectangle on concrete posts.	SEVEN	44 36	733.0	124 00	715.3	"	Radial Plot	1953	I				6055 ✓ 6058
LIGHT 19	White square house with black rectangle	DOW	44 35	1323.9	124 00	864.1	"	Triangulation Ph-113	1953	I				6055 ✓ 6058
LIGHT 20	White square house with red triangle	EBB	44 35	851.7	124 01	397.4	"	"	1953	I				6055 ✓ 6058
LIGHT 22	White square house with red triangle	FIN	44 35	107.5	124 01	360.1	"	"	1953	I				6055 ✓ 6058
LIGHT 25	White square house with black rectangle	FOG	44 35	32.8	124 00	885.3	"	"	1953	I				6055 ✓ 6058
LIGHT 30	White square house with red triangle	MAX	44 34	480	123 58	570	"	Radial Plot	1953	I				6055 ✓ 6058

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and *nonfloating aids* to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

* TABULATE SECONDS AND METERS

H. 2876-3

6 October 1953

The positions given have been checked after listing by C. J. Byrne

Chief of Party.

This form shall be prepared in accordance with Hydrographic Manual, pages 800 to 804. Positions of charted landmarks and *nonfloating aids* to navigation, if redetermined, shall be reported on this form. The data should be considered for the charts of the area and not by individual field survey sheets. Information under each column heading should be given.

FORM 537a
(9-24-47)

DEPARTMENT OF COMMERCE
COAST AND GEODETIC SURVEY

REGISTER NO. T -

(Destroyed.)

TOPOGRAPHIC TITLE SHEET

FIELD NO.

WCFP-A-53

Each Planetable and Graphic Control Sheet should be accompanied by this form, completed so far as practicable, when forwarded to the Washington Office.

STATE

Oregon

GENERAL LOCALITY

Newport, Oregon

LOCALITY

Yaquina Bay, Oregon

SCALE

1:5000

DATE OF SURVEY

5 May

, 19 53

VESSEL

West Coast Field Party

CHIEF OF PARTY

C. J. Beyma

SURVEYED BY

G. E. Haraden

INKED BY

G. E. Haraden

HEIGHTS IN FEET ABOVE MHW OR

☐ TO GROUND

☐ TO TOPS OF TREES

CONTOUR

APPROXIMATE CONTOUR

FORM LINE INTERVAL FEET

OBJECT NUMBER

CS-356

REMARKS

Applied to H-8039, H-8040 and H-8041 of 1953, and then destroyed

DESCRIPTIVE REPORT TO ACCOMPANY
TOPOGRAPHIC SURVEY SHEET WCFP-A-53

YAQUINA BAY OREGON

A. PURPOSE

The purpose of this survey was to locate additional control signals for the hydrographic survey of Yaquina Bay, Oregon, which could not be picked from photographs by the photogrammetric party.

B. EQUIPMENT

Planetable no. 105 and alidade no. H-223 were used for the topography.

C. TOPOGRAPHIC SHEET

The projection was drawn on an aluminum mounted topographic sheet and verified by officers of the West Coast Field Party. The shoreline was transferred from photo-manuscript T-9370.

D. PROCEEDURE

The following triangulation stations were plotted on the sheet for use in locating the hydrographic signals:

Yaquina Lighthouse Old, 1908
Coast Guard Lookout Tower
Sand, 1953
Yaquina Bar Front Range (USED) 1948
Yaquina Bar Rear Range (USED) 1948
Newport Center of Bridge Light 1950
Yaquina Bay Light 10 (USED) 1952
Boat Basin West Light (USED) 1950
Boat Basin East Light (USED) 1950

Four plane table set-ups were made and all signals to be located were cut in.

1. Set up over station SAND and oriented on all visible triangulation.
2. Set up on bank of south jetty near most westerly groin and oriented by three point fix.
3. Set up under highway bridge on south jetty and oriented by three point fix.
4. Set up on bank of north jetty south of Coast Guard Lookout Tower and oriented by three point fix

Approved & Forwarded
C. J. Beyma
C. J. Beyma
CDR., USC&GS
Chief of Party

Submitted by:
G. E. Haraden
G. E. Haraden
Ensign. USC&GS

H 8040

WCFP 1153

Oregpn
Approaches to
Yaquina Bay.

Processing Office Notes.

Smooth sheet.

The projection was ruled by hand on a cut sheet of D-117 paper. The shoreline and topographic signals are from T 11136, T11137, ~~T 9370~~. Δ stations are from the adjusted lithographed sheets for Oregon pages 28, 77 & 79.

Reefs.

The outstanding features of this sheet are the long reefs with shoal depths of 7 to 30 feet. These things are explained by the air photographs which show the shoal waters near shore. Here in the shallow water off Newport are seen the edges of vertical strata miles long and paralleling the shore. The strata are harder than the adjacent bottom. Knobby irregularities which the waves have not yet worn off appear on the strata. The strata are not visible in the deeper water further offshore where the reefs lay, but the reefs are believed to be of the same formation as the strata seem. See the reef along λ 124 05 from ϕ 4438 to Yaquina Head. South of the river entrance the reefs slant off to the southwestward. See the reef from ϕ 44 36.7 λ 124 04.95 to ϕ 44 38 λ 124 04.65, and from 35.95 04.70 to 35.30 05.15, and from 36.25 05.10 to 35.05 ~~06.0~~. This last is well marked to the south edge of the survey, but in deeper water.

Important soundings have been emphasized and pointed out with leaders. *in pencil.*

Curves.

The four fathom curve was omitted in places where it would cause confusion by crowding.

An eight fathom curve was used to delineate the reefs better. The ten fathom curve fell too far from the base of the reefs to outline them well.

The curves at the entrance to the river fit the curves on the inner sheet, H 8039.

The continuous profiles of modern surveys have so many advantages over hand lead or stop and go wire soundings that the older sheets are under a heavy handicap when compared.

see π 3
review

Comparison with Sheet H 3727, of 1914.

The jettys at the entrance to the river have been pushed out nearly half a mile and the soundings in the approach channel are importantly changed, some deeper, some shoaler, out to λ 124 05.5.

ϕ	λ	H 8040	H 3727
44 36.7	124 04.9	13	20
36.3	05.1	18.6	22
36.8	04.9	27	12

See TP 5
of Review

The older survey was not sufficiently close to reveal the nature of the reef running north from ϕ 44 38 along λ 124 05, nor the one running southwestward from ϕ 44 36.3 λ 124 05.1, nor the one from ϕ 44 04.75 λ 124 35.?

See TP 5
of Review

44 35 124 04.75

Comparison with H 4749.

In the vicinity of Yaquina Head the newer survey is in greater detail. Some shoal depths along the reef which follows λ 124 05 are in good agreement. The soundings of the older sheet frequently straddled the reef without revealing it.

The 21 foot sounding on H 8040 at ϕ 44 41.2 λ 124 04.82 does not appear on the older sheet.

The 3 2/6 fms. on H 4749 at ϕ 44 39.8 λ 124 06.06 falls about 100 meters north of a 21 foot depth on H 8040. The existence of the 3 2/6 fms. is not excluded. 20 ft. retained

44 35 124 04.75
See TP 5
of Review

Sunken rock at ϕ 44 39.8 λ 124 05.05 not found on H 8040.

Comparison with H 4894.

ϕ	λ	H 4894	H 8040	ϕ	λ	H 4894	H 8040
		Fms.	Feet.			Fms.	Feet.
44 40	124 07	23	144	44 41	124 06.5	21*	131.4
39	07	22	141.0	39	06.5	19	120
38.5	07	22	141.0	38.5	06.5	18	119
38	07	22*	139.1	38	06.4	18	114
37.5	07	21	137.4	34.5	06.5	12	78
37	07	20	132.1	34	06.5	13	53.5
36.5	07	19	129.3				
35.5	07	18	114.2				
34	07	16*	103.2				

* depth interpolated.

Considered in TP 5 of Review

Comparison was made along meridians 124 06, 124 06.5 & 124 07. On the western two lines the new survey tends to be about a fathom deeper than on H 4894. On the eastern of these meridians depths usually agree within two feet.

8040

Comparison with H 4879.

ϕ	λ	H 4879 Fms.	H 8040 Feet
44 39.	124 04.9	3 1/6	17 1/2
38.5	05.05	3 1/6	18 1/2
38.3	05.05	3	17
38	05.05	3 1/6	18 1/2
38	04.95	1 5/6	11 1/2
38.05	04.7	2 4/6	9 1/2
37.9	04.7	1 2/6	11 1/2
37.55	04.8	2 1/6	9 1/2
37.5	04.8	1 4/6	11 1/2
37.45	04.8	*	8 1/2
37.13	04.8	(a) 1 1/6	10 1/2

(a) = Carried forward to H-8040

* Print obscure

(b) - Sunkn. rks. not carried forward, they fall on left
charted sdgs. from 1950 USCGE survey (Bp 46608).
See TP 5 of Review

The reefs surveyed on H 4879 bear a close resemblance to H 8040. More frequently shoaler soundings were found on H 8040 than on H 4879. In the flattish area west of the reefs fathom differences can be found.

Several
shoaler
sdgs. on
reefs carried
forward to
H-8040

Comparison with Chart 6058.

ϕ	λ	Chart. Feet	H 8040. Feet
44 39.88	124 05.03	Sunk.Rk.	28'
35.8	05.45	12	10 1/2

See on Page 7 recommendation
that rock be deleted.

In general H 8040 shows shoaler soundings along the reef which runs along meridian 124 07 north from ϕ 44 38, but the chart shows shoaler depths on the reef running N X E from ϕ 44 36.7 λ 124 04.9.

The reefs running southwestward from ϕ 44 36.3 λ 124 05.1 and from 44 35.95 λ 124 04.75 are better developed on the new survey.

The limiting depths of 21 and 22 feet in the channel approach along the entrance range remains the same. This remark does not include depths in the channel between the jettys.

Edgar E. Smith
Cart. Engr.

4/13/54

STATISTICS FOR HYDROGRAPHIC SURVEY H-8040
FIELD SHEET NO. WCFP 1153

LAUNCH CS-160

Project CS-356

Vol. No.	Day Letter	Date	No. HL Soundings	No. Pos.	No. Stat. Miles Sdg.
I	a	6/12/53	-	140	23.6
II	b	6/22/53	-	40	6.9
II	c	6/26/53	-	53	10.5
II & III	d	7/1/53	-	123	24.1
III	e	7/7/53	-	78	15.3
III	f	7/8/53	-	31	7.1
III, IV & V	g	7/9/53	-	159	35.0
V & VI	h	7/27/53	-	178	32.3
VI & VII	j	7/29/53	-	118	26.2
VII & VIII	k	7/30/53	-	137	29.0
VIII	l	7/31/53	-	51	10.6
VIII & IX	m	8/17/53	-	69	10.7
IX	n	8/18/53	-	35	4.0
IX	p	8/20/53	-	75	10.4
X & XI	q	8/31/53	-	218	23.3
XI	r	9/1/53	-	175	26.2
XII	s	9/2/53	-	132	23.2
XII & XIII	t	9/3/53	-	129	25.6
XIII	u	9/8/53	-	45	3.8
TOTALS				1986	347.8
TOTAL SQUARE STATUTE MILES				20.72	

H 8040

WCFP 1153

Approaches to Yaquina Bay, Oregon.

List of geographic names
penciled on smooth sheet.

Yaquina Head

Yaquina Bay

Newport, Oregon

Agate Beach

Southbeach

Nye Beach

Yaquina Reef

South Reef

Names approved

10-11-54

a.j.w.

GEOGRAPHIC NAMES

Survey No. H-8040

Name on Survey	A On Chart No.	B On previous survey No.	C On U. S. quadrangle Maps	D From local information	E On local Maps	F P. O. Guide or Map	G Rand McNally Atlas	H U. S. Light List	K	
<u>Yaquina Head</u>										1
<u>Yaquina Bay</u>										2
<u>Newport</u>										3
<u>Agate Beach</u>										4
<u>Southbeach</u>										5
<u>Nye Beach</u>										6
<u>Yaquina Reef</u>										7
<u>South Reef</u>										8
										9
										10
										11
										12
										13
										14
										15
										16
										17
										18
										19
										20
										21
										22
										23
										24
										25
										26
										27
										M 234

Names approved
10-11-54
A.J.H.

DIVISION OF CHARTS
REVIEW SECTION - NAUTICAL CHART BRANCH
REVIEW OF HYDROGRAPHIC SURVEY

REGISTRY NO. H-8040

FIELD NO. WGFP-1153

Oregon, Newport, Approaches to Yaquina River

Project CS-356

Surveyed - June - Sept. 1953

Scale 1:10,000

Soundings:

Control:

808 Fathometer

Sextant fixes on
shore control

Chief of Party - C. J. Beyma
Surveyed by - C. J. Beyma and C. E. Haraden
Protracted by - C. R. Lehman
Soundings plotted by - C. R. Lehman
Verified and inked by - C. R. Helmer
Reviewed by - I. M. Zeskind 9-22-54
Inspected by - R. H. Carstens

1. Shoreline and Signals

The shoreline originates with reviewed air-photographic surveys T-11136 and T-11137 of 1953.

The source of the control is described in the Descriptive Report.

2. Sounding Line Crossings

Depths at crossings are in good agreement.

3. Depth Curves and Bottom Configuration

The usual depth curves are adequately delineated, except close inshore where breakers and foul areas generally prevented development of the bottom to the low-water line. Portions of the 8-fm. curve were drawn to better delineate Yaquina Reef.

A significant submarine feature in the area covered by the present survey is a long narrow reef which runs north-south,

north of the entrance to Yaquina Bay and southwest-northeast south of the entrance. The bottom inshore from the reef for the most part is very irregular, except in the northeast portion where it is fairly smooth. West of the reef the bottom is generally smooth. Ridges, troughs, deeps and pinnacles contribute to the bottom irregularity.

4. Junctions with Contemporary Surveys

An adequate junction was effected with H-8039 (1953) at the entrance to Yaquina Bay. The present survey extends to the limits of the project on the north, south and west, where charted depths are in adequate agreement with the present depths.

5. Comparison with Prior Surveys

- A. H-402 (1853), 1:375,000
H-998 (1868), 1:10,000

H-402 is a small-scale reconnaissance survey with only a few close inshore soundings falling in the area of the present survey. A comparison of H-402 with the present survey is deemed of no practical value.

A comparison between H-998 and the present survey reveals in general only minor differences of 2-3 ft. in depths, except along the submarine ridges and at the entrance to Yaquina Bay, where differences of as much as 8 ft. are noted. These latter differences in depths are attributed largely to the irregularity of the bottom in the vicinity of the ridges, the construction of the breakwaters at the entrance to Yaquina Bay and the action of the current on the bottom. Several soundings from H-998 have been brought forward to two shoals on the present survey.

With the addition of these prior soundings, the present survey is adequate to supersede the prior surveys within the common area.

- B. H-3727 (1914), 1:10,000

A comparison between the prior and present surveys shows that changes in bottom configuration have occurred principally on the east side of the submarine ridges which lie 1-2 miles offshore. The breakwaters at the entrance to Yaquina Bay have been extended seaward about $\frac{1}{2}$ mile, with resultant changes in bottom configuration. Here depths have changed as much as 19 ft., as for example,

in lat. $44^{\circ}37.01'$, long. $124^{\circ}04.52'$, where a prior depth of 12 ft. falls in present depths of 26-31 ft. On the west side of the ridges only minor changes in depths, of 2-4 ft. are noted. The ridges were not fully developed on the prior survey where sounding lines either straddled portions of the ridges or inadequately developed these features. Where soundings were obtained on the ridges on both the prior and present surveys, only minor differences of 1-2 ft. in depths were noted.

Several soundings from the prior surveys have been carried forward to the present survey. With these additions, the present survey is adequate to supersede the prior survey within the common area.

- C. H-4749 (1927), 1:20,000
H-4879 (1928), 1:20,000
H-4894 (1928), 1:40,000

These prior surveys together cover the area of the present survey. A comparison between the prior and present surveys reveals that in the area west of the submarine ridges there are only minor differences of 2-5 ft. in depths ranging from 60-130 ft., except in several places where the differences are greater. An example of this latter difference in depth occurs in lat. $44^{\circ}40.24'$, long. $124^{\circ}05.98'$, where a prior depth of 15 fms. falls in present depths of 97-101 ft. In the area east of the ridges minor differences of 2-3 ft. in depths are noted, except in the vicinity of the breakwaters where greater changes in depths have occurred, as for example, in lat. $44^{\circ}36.73'$, long. $124^{\circ}04.73'$, where a prior depth of 2-1/6 fms. falls in present depths of 22-24 ft. Prior general depths along the ridges are in harmony with present depths; however, a few shoaler soundings on the prior surveys have been carried forward to the present survey. The following discrepancies between the prior and present surveys were noted:

1. The sunken rock charted in lat. $44^{\circ}39.88'$, long. $124^{\circ}05.03'$ from H-4749, should be deleted from the chart. Close development of the area on the present survey discredits the existence of the sunken rock. Several sounding lines run over the area on H-4749 failed to confirm the existence of the feature. It is believed that kelp noted in the records was mistakenly identified as a sunken rock on H-4749. The soundings on the present survey are considered to adequately reveal the least depth in this area.

2. The following soundings (charted) which originate with H-4894 are believed to be in error because the visual fathometer by which these soundings were obtained was not operating properly at the time the fathometer was read. The soundings should be deleted from the chart.

<u>Charted depths</u> <u>Feet</u>	<u>Location</u>		<u>Present Survey</u> <u>Depths-Ft.</u>
	<u>Latitude</u>	<u>Longitude</u>	
72	44°39.23'	124°06.26'	105-108
96	44°39.24'	124°06.58'	120-133

With the addition of the several soundings and bottom characteristics, the present survey is adequate to supersede the prior surveys within the common area.

6. Comparison with Drawing of Chart 6058, dated 6/17/54
Chart 5902 (latest print date 5/4/53)
Chart 5802 (latest print date 8/9/54)

A. Hydrography

The charted hydrography originates principally with the previously discussed prior surveys which need no further consideration, with the U. S. Corps of Engineers' surveys accomplished subsequent to 1916, with several soundings which appeared on the first edition of Chart 6058 and whose sources are not readily ascertainable, and with critical depths from the boat sheet of the present survey. These boat sheet soundings differ from the smooth sheet soundings by 2 to 3 ft.

1. The following charted soundings which originate from sources other than this Bureau, should be retained on the chart. These soundings are either the least depths on the ridges or shoals in areas which have been inadequately developed on the present survey, or are soundings which fall in greater depths on the present survey and whose existence has not been disproved:

<u>Charted</u> <u>Sdg.-ft.</u>	<u>Latitude</u>	<u>Longitude</u>	<u>Source</u>
13	44°37.18'	124°04.42'	C of E 1935 (Bp 28702) (Bp 27571) (Bp 27771)
8	44°37.20'	124°04.81'	C of E 1916 (Bp 16345)
8	44°37.08'	124°04.85'	C of E 1916 (Bp 16345)
6	44°36.98'	124°04.85'	C of E 1950 (Bp 46608)
8	44°36.90'	124°04.88'	" " " "
6	44°36.85'	124°04.88'	" " " "

6	44°36.80'	124°04.88'	C of E 1950 (Bp. 46608)
5	44°36.72'	124°04.92'	" " " " (" ")
10	44°36.66'	124°04.94'	" " " " (" ")
16 Rk	44°36.68'	124°04.52'	" " " " (" ")
2 Rk	44°36.60'	124°04.44'	" " " 1925 (" 19898)
3 Rk	44°36.52'	124°04.40'	" " " 1929 (" 22724)
6	44°36.40'	124°04.42'	" " " 1940 (" 34674)
8	44°36.45'	124°04.43'	" " " 1940 (" 34674)
15	44°36.80'	124°04.50'	" " " 1949 (" 45818)
15	44°36.22'	124°05.13'	1st Ed. Cht. 6058 (1916)
15	44°35.94'	124°05.31'	" " " " " "
14	44°35.83'	124°05.27'	" " " " " "
17	44°35.82'	124°05.22'	" " " " " "
17	44°35.77'	124°05.27'	C of E 1916 (Bp. 16345)
4 Rk	44°37.57'	124°04.25'	1st Ed. Cht. 6058 (1916)
8	44°37.32'	124°04.80'	C of E 1930 (Bp. 23495)

2. The sunken wrecks charted in lat. 44°36.0', long. 124°06.0', and lat. 44°37.0', long. 124°06.0' respectively on Chart 5802 from H.O. Wreck List dated January 1, 1943, fall on the present survey in depths of 70-80 ft. The existence of these wrecks was neither confirmed nor disproved on the present survey. The sunken wrecks should, therefore, be retained on Chart 5802.

*Non-damaged wrecks
omit on chrt 6058*

3. The 20-ft. sounding charted in lat. 44°40.13', long. 124°04.30' was erroneously revised from a 29-ft. sounding on Chart 6058, dated 7/12/35. The charted 20-ft. sounding should be disregarded.

The present survey supersedes the charted hydrography, except for those charted soundings listed for retention in paragraph 1 above and soundings charted from Corps of Engineers' surveys made subsequent to the present survey.

B. Aids to Navigation

The present survey positions of aids to navigation are in substantial agreement with the charted positions and adequately mark the features intended.

C. Dredged Channels

The controlling depth in the dredged channel into Yaquina Bay originates with the U. S. Corps of Engineers' survey of 1954 (Bp. 51628) which was accomplished subsequent to the present survey.

7. Condition of Survey

- a. The sounding records and Descriptive Report are complete and comprehensive.
- b. Numerous discrepancies at crossings and between adjacent lines were eliminated by rescanning profiles showing heavy chop. Phase corrections were applied to 160 soundings and errors in reductions were found in 71 soundings.

8. Compliance with Project Instructions

The survey adequately complies with the Project Instructions.

9. Additional Field Work Recommended

The present survey together with the soundings recommended for retention on the charts provide adequate coverage of the area.

Examined and approved:




H. R. Edmonston
Chief, Nautical Chart Branch



E. R. McCarthy
Acting Chief, Division of Charts



G. R. Fish
Chief, Hydrography Branch



Earl O. Heaton
Chief, Division of Coastal Surveys

H 8040

8040

Processing Office Notes.

Hydrographic Surveys (Chart Division)

HYDROGRAPHIC SURVEY NO. H-8049...

Records accompanying survey:

Boat sheets; sounding vols. ¹³; wire drag vols.;
bomb vols.; graphic recorder rolls ^{new};
special reports, etc. ^{1 smooth sheet, 1 Descriptive Report}
.....

The following statistics will be submitted with the cartographer's report on the sheet:

Number of positions on sheet	1986

Number of positions checked	117

Number of positions revised	31

Number of soundings revised (refers to depth only)	865 *

Number of soundings erroneously spaced	28

Number of signals erroneously plotted or transferred	0

Topographic details	Time 4

Junctions	Time 4

Verification of soundings from graphic record	Time 20

Verification by *C.R. Helmer* Total time 379 Date 9/1/54

Reviewed by *Lu Zeslund* Time 103 Date 9/23/54

Sub because of
* includes 161 phase corrections and 71 arithmetical errors. Numerous changes
because of chop

1974

H 8040

★ (5550) OREGON—Yaquina Bay—Gong buoy replaced by buoy.—Yaquina Bay North Jetty Gong Buoy 5 has been seasonally replaced by a second-class can painted black and numbered 5.

Approx. position: 44°36'47" N., 124°04'38" W.

Note.—The gong buoy will be maintained from May 1 to October 1, annually, and the second-class can from October 1 to May 1, annually.

(See N. M. 38 (5306) of 1951.)

(Supersedes N. M. 40 (5172) of 1953.)

(N. M. 43, Oct. 24, 1953.)

(L. N. M. 155, C. G., Seattle, Oct. 7, 1953.)

C. & G. S. Chart 6058.

C. G. Light List, Pacific Coast, 1953, page 83.

C. & G. S. Coast Pilot, Pacific Coast, 1951, page 326.

★ (5551) COLUMBIA RIVER—Baker Bay East Channel—Buoys moved.—The following buoys have been moved and reestablished as indicated to better mark the channel; distances and bearings from Baker Bay East Channel Light 10 (46°16'24" N., 123°58'41" W.):

(a) Baker Bay East Channel Buoy 14, in 6 feet of water, about 1,600 yards 286°.

(b) Baker Bay East Channel Buoy 20, in 10 feet of water, about 3,420 yards 301°.

(c) Baker Bay East Channel Buoy 26, in 10 feet of water, about 5,325 yards 303°.

(See N. M. 32 (4212) of 1953.)

(N. M. 43, Oct. 24, 1953.)

(L. N. M. 157, C. G., Seattle, Oct. 9, 1953.)

C. & G. S. Chart 6151.

C. G. Light List, Pacific Coast, 1953, page 138.

C. & G. S. Coast Pilot, Pacific Coast, 1951, page 345.

★ (5552) COLUMBIA RIVER—St. Helens to Willamette River—Leading light established.—A leading light showing *quick flashing white*, of 600 candle-power visible between the bearings 143° 30' and 151° 30' (toward the light), has been established 15 feet above the water on the structure of Fales Light 17.

Approx. position: 45°46'34" N., 122°45'47" W.

(N. M. 43, Oct. 24, 1953.)

(L. N. M. 156, C. G., Seattle, Oct. 8, 1953.)

C. & G. S. Chart 6154.

C. G. Light List, Pacific Coast, 1953, No. 1196.

C. & G. S. Coast Pilot, Pacific Coast, 1951, page 354.

RHC

TIDE NOTE FOR HYDROGRAPHIC SHEET

~~DIVISION OF COASTAL SURVEY~~

4 June 1954

Division of Charts: R. H. Carstens

Plane of reference approved in
13 volumes of sounding records for

HYDROGRAPHIC SHEET 8040


Locality Yaquina River, Oregon

Chief of Party: C. J. Beyma in 1953
Plane of reference is mean lower low water, reading
3.2 ft. on tide staff at Newport
17.2 ft. below B. M. 5 (1933)

Height of mean high water above plane of reference is 7.3 feet.

Condition of records satisfactory except as noted below:

E. C. McKay
Tides Branch
Chief, Division of Tides and Currents.



NAUTICAL CHARTS BRANCH

SURVEY NO. H-8040

Record of Application to Charts

[illegible]

M-2168-1

A basic hydrographic or topographic survey supersedes all information of like nature on the uncorrected chart. Give reasons for deviations, if any, from recommendations made under "Comparison with Charts" in the Review.