9898×

Diagram No. LS-5

NOAA FORM 76-35A

U.S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION NATIONAL OCEAN SURVEY

DESCRIPTIVE REPORT

Type of Survey	<u>Hydrographic</u>
Field No.	WH-20-2-80
Office No	H-9898
×**	
	LOCALITY
State	Michigan
	-ake Huron
	Port Sanilac to
	exington Heights
t en	19 80
	CHIEF OF PARTY
<u></u>	DR.F.P.Rossi
	RARY & ARCHIVES
DATE	ovember 16, 1981

학U.S. GOV. PRINTING OFFICE: 1980---868-537

AREA-7 CHARTS

14800 cleared

FORM	C&GS-537

U.S. DEPARTMENT OF COMMERCE ENVIRONMENTAL SCIENCE SERVICES ADMINISTRATION COAST AND GEODETIC SURVEY

REGISTER NO.

HYDROGRAPHIC TITLE SHEET

н-9898

INSTRUCTIONS - The Hydro	ographic Sheet shoul	d be accompanied by	this form,
filled in as completely as pe	ossible, when the sh	eet is forwarded to th	ae Office.

FIELD NO.

WH-20-2-80

State MICHIGAN	
General locality LAKE HURON	
Locality SOUTH WEST COAST PORT SANILAC TO LEXINGTON HEIGH	<u>TS</u>
Scale 1:20,000 Date of survey 23 JULY - 9 OCTOBER	L980
Instructions dated 31 MARCH 1980 Project No. OPR-X115-WH-80	
essel NOAA SHIP WHITING Launchs 1014, 1015, and Monark 1288	<u></u>
Chief of party CDR Frank P. Rossi	
Surveyed by J.C. Gardner, R.G. Mann, D.A. Bland, J.B. Grant	·
Soundings taken by echo sounder, 根格数据根据表 ROSS Model 5000 RATTHEON DE 719 E	<u> </u>
Graphic record scaled by WHITING personnel	·
Graphic record checked by JCG, RGM, DAB, JBG, RWB	
Protracted by Automated plot by HYDROPLOT	
Soundings penciled by	
Oundings in ###### feet at MEW LWD (IGLD 1955:576.8 FT)	
REMARKS: All times are Coordinated Universal Time	
Notes in red made during verification.	
<u> </u>	_
SIANDARDS CHECKED 11-8-82.	
Clon	

A. PROJECT

Hydrographic Survey H-9898, WH-20-2-80, was performed in accordance with Project Instructions for OPR-X115-WH-80, Lake Huron dated March 31, 1980, as amended by the following changes.

Change No.	Date
1	04/04/80
2	04/11/80
3	04/23/80
4	05/21/80
5	07/16/80
6	07/23/80
7	09/09/80
/	·

B. AREA SURVEYED

Survey H-9898 was run from July 23 to October 9, 1980, JD's 205-283. The survey extends north from 43°13.2'N to 43°26.1'N.

60-foot

The survey is bounded by approximately; the 20-meter curve in the east and the 5-fathom curve in the west. The western limit of the survey area was extended in the area of Lexington, Michigan, to junction with survey H-9899, WH-5-4-80, Lexington Harbor and in the area of Port Sanilac, Michigan, to junction with a 1:5,000 survey of the Port Sanilac Harbor, which is included with this survey.

C. SOUNDING VESSELS

The sounding vessels used in this survey was WHITING launches 101 1015, and MonArk 1288, EDP numbers 2932, 2931, and 2933

respectively. All hydro on the southern end of the sheet was run with Launch 1015, the north end of the survey area and Port Sanilac was run with Launch 1014. The inside of Port Sanilac was run with the MonArk.

The launches were equipped with standard hydrographic equipment.

The MonArk was powered with a Johnson 85-HP outboard motor and made use of a Raytheon shallow water fathometer. No major mechanical problems were encountered with any of these vessels.

D. SOUNDING EQUIPMENT AND CORRECTIONS TO ECHO SOUNDINGS

The launches (1014 & 1015) were equipped with a Ross Model 5000 fathometer (s/n 1049 and 1087 respectively). Phase calibrations were conducted regularly in accordance with the ROSS operating manual. Analog and digital outputs compared satisfactorily. The MonArk was equipped with a Raytheon Model DE-719B fathometer (s/n 465). Calibrations were done in accordance with the Raytheon operating manual. The draft correction of the MonArk (1.0 ft) was set on the Raytheon fathometer for the day it was used (JD 260) so no TRA correction is applied on the corrector tape.

Bar checks were taken daily, weather and sea conditions permitting. TDC casts were taken with a Martek TDC unit, Model No. 167 ($\rm s/n$ 127).

When the correctors were determined from the bar check averages and graphed, there was a difference between the curves for launches 1014 and 1015 (average of .5 ft). The source of this error has not been completely determined, but it will be further investigated by the Electronic Engineering Division during the up-coming inport at the Atlantic Marine Center.

Velocity curves were taken off the individual bar check averages and then extrapolated to the deepest survey depths from the TDC data. See Verification Report, Section 1.6.

It was determined that the fresh water TRA corrector of the WHITING launches was 1.7 feet instead of the 1.5 feet that was being used. All data before JD 236 (23 August 1980) used a corrector of 1.5, after that date 1.7 was used. This difference was taken into consideration when making up the TC-TI tape and the additional correctors are applied there.

Settlement and squat trials were run on launches 1014 and 1015 in Lake Huron, Michigan, in July and September 1980. Trials were run at a point of known depth, marked by a buoy. Results are the average of one run towards the buoy and one run away from the buoy with marks being taken when the buoy was abeam the transducer. The

speeds and results are listed below.

SPEED IN RPM's	CORRECTION 1014	CORRECTION 1015
600	+0.10	+0.00
800	+0.10	+0.10
1000	+0.30	+0.10
1200	+0.30	+0.20
	+0.30	+0.20
1400	+0.30	+0.30
1600	+0.30	+0.40
1800		+0.10
2000	+0.40	+0.10
2200	+0.20	
2400	-0.10	-0.20
2600	-0.40	-0.40

The settlement and squat graphs are included in the appendix.

Corrections for settlement and squat are made on the TC/TI Tape.

Periods of reduced speed during actual hydrography are noted in the sounding volumes and on the printouts.

The MonArk was run at idle speed and there is no settlement and squat correction or TC/TI Tape for this vessel.

E. HYDROGRAPHIC SHEETS

The survey area was divided into two 1:20,000 plotter sheets (skew = 90°) and one 1:5,000 plotter sheet of Port Sanilac Harbor (skew = 0°) with the following origins.

North: 43°19'00"N

82°25'00"W

South: 43°12'30"N

82°25'00"W

Sanilac Harbor: 43°12'30"N 82°32'30"W

The 1:20,000 survey has a total of 4 plotter sheets; two sheets show the crosslines and mainscheme hydrography, the two other sheets show the development hydrography and bottom samples. The Port Sanilac Harbor was surveyed at a 1:5,000 scale but the final plot consisted of one 1:2,500 scale sheet showing all hydrography and bottom samples.

F. CONTROL STATIONS

The following stations were used as ARGO stations, calibration signals, calibration points, Range-Azimuth set-up sites or Range-Azimuth initial points.

Signal No.	Description	Light	List No.
100	Casey, 1980 (Sanilac Argo Site)		
102	Poth, 1980 (Bayfield Argo Site)		
104	H-2-MI-79 (Port Huron Argo Site),	1979	
132	H-32-MI-79, 19 3 9		
113	Lexington E. Brk Light, 1979		1232
1 1 4	Lexington W. Brk Light, 1979		1232.1
133	H-33-MI-79, \97 9		
115	Corps of Engineers "B", 1979		
116	Corps of Engineers "D", 1979		100/ 5
117	Sanilac S. Brk Light, 1975		1234.5
118	Sanilac N. Brk Light, 1975		1234
119	Sanilac Lighthouse, 1886		1233
120	Sanilac E-Cal, 1980		
121	Sanilac W-Cal, 1980		
241	H-32-MI-80-Ca1, 1980		

Stations 100-119 were either established or verified by third order traverse in 1979, run by the Hydrographic Survey Branch,

Atlantic Marine Center. Stations 120, 121, and 241 were established by WHITING personnel and were used only for daily calibration of the electronic positioning systems. They are non-recoverable stations.

A signal list is included in the appendix.

G. HYDROGRAPHIC POSITION CONTROL

Range-Range control was used on all of the 1:20,000 scale survey. Range-Azimuth was used for the 1:5,000 scale sheet. The ARGO positioning system was used for all Range-Range work. On the Range-Azimuth survey the Del-Norte positioning system was used to measure the ranges and the azimuths were measured with a Wild T-2 theodolite.

Baseline calibrations were conducted on the Del-Norte system in accordance with the <u>Hydrographic Manual</u> over a baseline of 2036 meters. All calibration records are included with the field records.

Daily correctors were computed and applied by three-point sextant fixes with a check angle or by positioning the Del-Norte Master unit or ARGO antenna on a known baseline. In general, both of the positioning systems performed satisfactorily through out the survey period. Errors were made when computing lane values for the calibration points, by using an incorrect value for converting

meters into lanes. This error was discovered, corrected and the daily partial lane correctors were changed to eliminate the discrepancy.

The following is a list of component serial numbers for the ARGO, Del-Norte and Wild equipment:

Launch 1015 (2931) CPU - CO47824 JD's 204-212 RPU - RO47851 RPU - RO379119 CPU - CO37953 JD's 232-240 Launch 1014 (2932) CPU - CO47822 JD's 209-254 RPU - R047843 Remote (code 74) 218,T-2 -35052 Master - 169 JD's 255-256 DMU - 162 Remote (code 76) 216,T-2 -35052 DMU - 192 Master - 1160 283 Monark 1288 (2933) Remote (code 74) 218,T-2 -35052 DMU - 162 Master - 169 JD 260

H. SHORELINE Saa Verification Report, saction 2.b.

No shoreline manuscripts were available for this survey. The shoreline for the 1:5,000 survey of the Port Sanilac Harbor will come off an insert of NOS Chart 14862, (1:20,000) 23rd Edition, 1978.

I. CROSSLINES

The percentage of crosslines on the 1: 20,000 scale survey was 11.0% and the total miles of crosslines was 48.7.

On the 1:5,000 scale section there was 3.4 miles of crosslines which was 36.0% of the hydrography done on this sheet.

Agreement with the main scheme was good (0-2 feet).

J. JUNCTIONS See also Verification Report, Section 5

(1980)
This survey junctions with H-9895 (1:20,000) in the south, with

H-9899 (1:5,000 Lexington Harbor) on the western shoreline of the

(1980)
southern sheet and with H-9906 (1:20,000) in the north. These surveys

were also conducted by WHITING personnel this year and have not

been verified. There is good junction between these surveys and

(1980)
H-9898 (0-2 feet).

This survey was also compared with a Canadian Hydrographic Survey, (1980)
number 3831, (1:100,000), 1974. Survey H-9898A(south sheet)
showed depths of 3 to 15 feet deeper than the CHS survey with an average of 6 feet deeper. The North sheet of H-9898A showed depths
of 4 to 16 feet deeper with an average of 8 feet deeper than the
CHS survey. Sax later attached. Sax ass Varification Report, Section 6

Corps of Engineers Lake Survey, File numbers 1-1970, sheet 3 of 7, (1950)

1-1971 sheet 4 of 7, 1-1972 sheet 5 of 7 and 1-1973 sheet 6 of 7, (1950)

was also compared to survey H-9898. The South sheet of H-9898(1980) showed depths of 0-7 feet deeper with an average of 3 feet deeper than the Corp of Engineer surveys. The North sheet of H-9898(1980) showed depths of 0-5 feet deeper with an average of 4 feet deeper than the Corp of Engineer surveys.

The lake level was between 2 and 3 feet above the International Great Lakes Datum of 1955 during the survey period, but this was not taken into consideration during the comparisons with junctioning surveys.

L. COMPARISON WITH THE CHART (Also see Section P)

Survey H-9898 was compared with NOS Chart 14860, (1:120,000),

23rd Edition, July 20, 1978. The survey soundings differ from the chart by 3 to 15 feet deeper with an average of 7 feet deeper.

The survey of Port Sanilac Harbor was compared to the 1:5,000 inset of the Sanilac Harbor on the same chart as listed above. The survey surrounding Sanilac shows depths of 0-7 feet deeper with an average of 4 feet deeper than the chart.

The lake level was not considered in these comparisons, Chart Smooth sheet depths.

Development 2N Spike Investigation

JD 246 Positions 5619-5625

This spike was discovered on the main scheme on JD 237, (between 3rd and 4th out of Position #5317). A star pattern development was run over the spike. A detached position was also taken on the spike, (Lat 43/22/43N and Long 82/30/47W), but the fathometer least depth observed (34.6 ft) occurred between 2nd and 3rd out of Position #5624. The fathometer trace appears to show that the area surrounding the spike is rocky and the spike appears to be a large rock

extending 4 feet off the bottom.

It is recommended that this spike be charted as "RK 34 ft". Chart smooth

The lake level above the IGLD was not considered in reducing the least depth.

Development 3N Spike Investigation JD 246 Positions 5626-5632

This spike, was discovered on the main scheme on JD 237, (between 3rd and 4th out of Position #5241). A star pattern development was run over the spike. The feature was also observed between, (1st and 2nd out of Position #5627), (1st and 2nd out of Position #5629), and (2nd and 3rd out of Position 5631). The observed position of these are in the vicinity of spikes is, Lat. 43/21/48N and Long. 82/31/02W. As in development 2N the spikes appears to be a rocks extending 3 feet off the bottom with a fathometer least depth of 2%. S, feet.

It is recommended that this spike be charted as "Rks 27 ft".

least depth. Successful depths and the note Rks.

Development 4N Spike investigation (29.5') JD 246 Positions 5633-5638

This spike, was discovered on the main scheme on JD 237 (just before

Position #5223). A star pattern development was run over the lat 43° 21'29.4", long 82° 30'48.8"

spike. The spike was observed between; (2nd and 3rd out of 30.0' 30.5'

Position #5633), (2nd and 3rd out of Position #5635) and (2nd 283' and 3rd out of Position #5637). The observed position of these are in the vicinity of 27 spikes is Lat. 43/21/30N and Long. 82/30/47W. Thise feature from 2 to 4 appears to be a group of rocks extending 3 feet off the 28.3 bottom with a fathometer least depth of 32.7 feet.

It is recommended that this feature be charted as "Rke 32 ft".

The lake level above the IGLD was not considered in reducing the least depths. Charl smooth shoot depths and note Rks

M. ADEQUACY See Var. Firstian Report also
This survey is adequate to supercede the chart in the area surveyed.

N. AIDS TO NAVIGATION Saw Varification Report Saction 7.C.

There are no floating aids to navigation in the survey area of H-9898.

O. STATISTICS

Total number of positions per launch:

	<u>-</u>	1:20,000 sheet	1:5,000 sheet
VESNO	2931	1325	
VESNO	2932	638	216
VESNO	2933		_63
		1963	279

TOTAL: 2242

Total Miles of soundings per launch:

	1	L:20,000	1:5,000 sheet
VESNO	2931	322.6	
VESNO	2932	164.6	11.6
VESNO	2933		1.3
		487.2	12.8
TOTAL:	500.0 1	miles	

Water Level Gages established: One (1).

MISCELLANEOUS

On JD 254 dives were made on a charted wreck on survey H-9899, (WH-5-4-80 Lexington Harbor), and positions were taken on the wreckage found. wreck. Since the positions were taken with the ARGO position system not accurate enough for a 1:5,000 survey the position numbers were changed and all data was transferred to this survey, (1980) H-9898 (1:20,000). 13Wk from Prior survey LS-1970(1950) was also retained 24 124,43.15.74 N, long 82-30.67 W. Change Number 7 to the Project Instructions, concerning the survey of the Port Sanilac Harbor, was not received until after the survey was completed. The hydrography on this 1:5,000 survey extends beyond the limits set forth in Change Number 7.

A discussion with Lt. J. C. Gardner, who took part in the divers, revaled the wrack was brokening and visibility poor. A 17 foot echo sounder depth at Pos. 1301
least depth was obtained over this extensive brokening wrack becalalivers also indicated that two schooners sunk in the vicinity in the early 1900's.

Q. RECOMMENDATIONS

It is recommended that this survey supercede the chart in the area bounded by the survey limits.

R. AUTOMATED DATA PROCESSING

Program No.	Description	<u>Version Date</u>
FA181 RK112 RK201 RK211 RK212 RK216 RK300 RK330 AM407	Range-Azimuth Hydrolog Range-Range/Hyperbolic Real-Time Hydroplo Grid, Signal & Lattice Plot Range-Range Non-Real Time Plot Visual Station Table Load Range-Azimuth Non-Real Time Plot Utility Computations Reformate and Data Check Geodetic Inverse/Direct Computations Layer Correctors for Velocity	02/23/78 08/22/80 04/18/76 01/15/76 04/01/74 02/05/76 02/05/76 05/04/76 10/25/75 05/19/75
AM530	Hyperbolic & Range-Range Geodetic Calibration	n 02/19/75
RK561 AM602	Extended Line Oriented Editor	05/20/75

S. REFERENCES TO REPORTS

None.

Submitted By: fames C. Dardner

James C. Gardner, Jr. LT(jg), NOAA

Supervision of all field and office work on this hydrographic survey was continuous on a day to day basis to ensure completeness of the survey and all work was done in accordance with the Project Instructions.

Approved/Forwarded

Frank Moses

Frank P. Rossi Commander, NOAA

Commanding Officer, NOAA Ship WHITING



U.S. DEPARTMENT OF COMMERCE National Oceanic and Atmospheric Administration NATIONAL OCEAN SURVEY NOAA Ship WHITING A39 W York Street

439 W. York Street Norfolk, Virginia 23510

November 14, 1980

T0

AMC Processing, OA/CAM

FROM

Commander Frank P. Rossi, NOAA

Commanding Officer, NOAA Ship WHITING

SUBJECT:

1980 Lake Huron Surveys: Depth Descrepency between

WHITING's Surveys and Canadian Surveys.

In late October I talked with Ross Douglas, Canadian Hydrographic Service, Burlington, Ontario, about our junction problem with the Canadian Surveys. He said that they were having problems with these Canadian Surveys, and indicated they were rejecting some of the work. The surveys were primarily for limnological studies and hydrographic use of them was secondary.

The fact that our junctions get worse the further one is from Port Huron - Sarnia would indicate that the CHS may be experiencing a problem with the propagation velocity they used. They did not calibrate the Mini-Fix on the United States side of their work. A modest error in the propagation velocity will produce a considerable position error when carried to distances greater than 30 miles.

The WHITING generally did not work more than 15 miles from a calibration site; therefore, there should be little error (less than 10 meters) in the WHITING's positions.



SIGNAL TAPE

WH-20-2-80

H-9898

```
-001 100 6 43 26 00309 082 32 20465 250 0000 164510 Casey,1980 002 102 6 43 34 20443 081 42 30102 250 0000 164510 Poth,1980 003 104 6 43 00 23671 082 25 21248 250 0000 164510 H-2-MI-79 004 132 6 43 15 04535 082 31 26752 139 0000 000000 H-32-MI-79 005 133 6 43 14 28565 082 31 25148 139 0000 000000 H-33-MI-79 006 113 6 43 15 59799 082 31 22233 139 0000 000000 Lexington E. Brk. Light,1979 007 114 3 43 16 02820 082 31 24754 139 0000 000000 Lexington W. Brk. Light,1979 008 115 6 43 25 52149 082 32 05288 250 0000 000000 C. of E. "B",1979 009 116 6 43 25 58103 082 32 15226 250 0000 000000 C. of E. "B",1979 010 117 6 43 25 51700 082 32 08976 139 0000 000000 Sanilac S. Brk. Light,1975 012 119 6 43 25 44430 082 32 24708 139 0000 000000 Sanilac N. Brk. Light,1975 012 119 6 43 25 44430 082 32 24708 139 0000 000000 Sanilac N. Brk. Light,1975 013 241 6 43 15 04550 082 31 26101 243 0000 000000 Sanilac E. Gal,1980 015 121 3 43 25 48998 082 32 05664 243 0000 000000 Sanilac W. - Cal,1980
```

NOAA FORM 76-40 (8-74)	- 40					I.S. DEPARTM	U.S. DEPARTMENT OF COMMERCE	ORIGINATING ACTIVITY	ACTIVITY
Replaces C&GS Form 567.	m 567.	ATING AIDS OR LANDWARKS FOR CHARTS	IDMARKS	FOR CH	ARTS	AT MOSPHER	IC ADMINISTRATION	MHYDROGRAPHIC PARTY GEODETIC PARTY	ARTY
TO BE CHARTED	RTED REPORTING UNIT	e) STATE		LOCALITY			DATE	COMPLATION ACTIVITY	4 TY V TY
TO BE DELETED		G Michigan	ď	Lexing	Lexington/Sanilac	ilac		OUALITY CONTROL & REVIEW GRP.	L & REVIEW GRP.
The following objects	objects HAVE HAVE NOT	been inspected from seaward to determine their value as landmarks	award to de	etermine the	ir value as	· landmarks.		(See reverse for responsible personnel)	sible personnell
V115_tM_80		SURVEY NUMBER	NAD 1	1927					
, IIII CTTV		n-9090		POSITION	NOI		(See instructions on reverse side)	on reverse side)	CHARTS
CALFORNIC	DESCRIPTION	NO	LATI	LATITUDE	LONG	LONGITUDE			AFFECTED
NAME	(Record reason for deletion of landmark br aid to navigation. Show triangulation station names, where applicable, in perentheses	rk br eid to navigation. re applicable, in perentheses	, ,	// D.M. Meters	, .	// D.P. Meters	OFFICE	FIELD	
Tank FR	Lexington West Tank FR Croswell Tank	X.	43/16	45.5	82/36	40.5		V18 72080	14862
Stack	Lexington West Stack Michigan Sugar Co. Stack	ack	43/16	0.00	82/36	56.5		VAS (80	14862
Spire	Lexington S. Spire Trinity Episcopal Church Spire	rch Spire	43/15	56,1	82/31	53.0		7/780	14862
Tank	Lexington Tank		43/16	08.1	82/32	15.0	·	7.20/80	14862 14860
	Port Sanilac N. Breakwater	ater Lt. 2	43/25	48.99	83/32	05.30		F-2-6-L 1979	14862
	Port Sanilac S. Breakwater	ater Lt. 3	43/25	51.70	82/32	08.98		F-2-6-L 1979	14862
	Port Sanilac Lt.		43/25	44.43	82/32	24,71		F-2-6-L 1979	14862 14500 14860
	1-7	-1290(82)			•				
	·								
	. **								
				1					

.--

-

GEODETIC PARTY

PHOTO FIELD PARTY

COMPILATION ACTIVITY

FINAL REVIEWER

QUALITY CONTROL & REVIEW GRP.

COAST PILOT BRANCH (See reverse for responsible personnel) AFFECTED CHARTS 14860 14860 14860 14862 ORIGINATING ACTIVITY K HYDROGRAPHIC PARTY GEODETIC PARTY METHOD AND DATE OF LOCATION (See Instructions on reverse side) FIELD F-2-6-L 1979 F-2-6-L 1979 U.S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION DATE OFFICE D.P. Meters been inspected from seaward to determine their value as landmarks
SURVEY NUMBER DATUM 22.23 24.75 LONGITUDE 82/31 82/31 Lexington NONFLOATING AIDS OR LANDMARKS FOR CHARTS POSITION LOCALITY D.M. Meters 59.80 02.82 NAD 1927 LATITUDE 43/15 43/16 0 Michigan DESCRIPTION \ (Record reason for deletion of landmark or aid to navigation. Show triangulation station names, where applicable, in parentheses, -1290(82) H-9898 Lexington Harbor E. Brk. Lt. Lexington Harbor W. Brk. Lt NOAA Ship WHITING REPORTING UNIT The following objects HAVE HAVE NOT OPR PROJECT NO. Replaces C&GS Form 567. TO BE CHARTED TO BE DELETED X TO BE REVISED X115-WH-80 NOAA FORM 76-40 (8-74) CHARTING

SUPERSEDES NOAA FORM 76-40 (2-71) WHICH IS OBSOLETE, AND EXISTING STOCK SHOULD BE DESTROYED UPON RECEIPT OF REVISION,

NOAA FORM 76-40 (8-74)

EIPT OF REVISION, 本 U. S. GPO:1975-0-865-080/1155

VELOCITY TABLE I

JD's 205-211 VESNO 2931

000020 0 0000 0001 000 293100 009898 000060 0 0002 000200 0 0004 000670 0 0006 000800 0 0004

VELOCITY TABLE II

999999 0 0000

JD's 206-212 VESNO 2932

000205 0 0000 0002 000 293200 009898 000420 0 0002 000635 0 0004 000800 0 0006 999999 0 0000

VELOCITY TABLE III

JD's 232-238 VESNO 2931

000052 0 0000 0003 000 293100 009898 000114 0 0002 000180 0 0004 000265 0 0006 000620 0 0008 000730 0 0006 000800 0 0004 999999 0 0000

VELOCITY TABEL IV

JD's 236-246 VESNO 2932

000200	1	0002	0004	000	293200	009898
000275	0	0000				
000355	0	0002				
000567	0	0004				
000690	0	0002				
000770	0	0000				
999999	0	0000				

VELOCITY TABLE V

JD's 255-283 VESNO's 2932 & 2933

000050	1	0002	0005	000	293200	009898
000170	1	0004				
000430	1	0002				
000840	1	0004				
999999	0	0000				

Field water level reductions were not performed on hydrographic survey H-9898. WHITING personnel installed and monitored a water level gage located at Port Sanilac; Lat. 43°26.0'N and Lon. 82°32.2'W.

A primary gage at Lakeport was installed by the Army Corps of Engineers and is monitored by a paid observer. This gage is located at Lat. 43008.5'N and Lon. 82029.5'W. This gage was found to be in proper working order.

U.S. DEPARTMENT OF COMMERCE NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION NATIONAL OCEAN SURVEY

WATER LEVEL NOTE FOR HYDROGRAPHIC SHEET

Processing Division: Atlantic Marine Center: CAM3

Hourly heights are approved for

Water Level Station Used: Port Sanilac, Michigan (907-5011)

Period: July 25, 1980 - October 11, 1980

HYDROGRAPHIC SHEET: H - 9898

OPR- X115-WH/HSB - 80

Locality: Lake Huron

Plane of reference: Low Water Datum (IGLD 1955 : 576.8 Feet)

Remarks: Zoning not required. Data form other gages on Lake Huron indicates no unusual water level movement during the survey

period.

NOAA FORM 76-155 U.S. DEPARTMENT OF COMMERCE (11-72) NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION						UMBER				
GEOGRAPHIC NAMES (FLELD)								н-9898		
Name on Survey	A	OH CHART N	ord Bod on Con	OUP EN DE	ANGLE COM LOCAL COM LOCAL COM LOCAL	or Local W	APS GUIDE	OR MAP OR MAP AMONENAS	J.S. LIGHT	ist
LAKE HURON	х									1
LEXINGTON	х									2
PORT SANILAC	х									3
PORT SANILZC HARBOR (TO	-X-									4
LEXINGTON HEIGHTS										5
, , , , , , , , , , , , , , , , , , , 										6
	ļ				ļ					7
100 March 200 and 100							ļ	<u> </u>		8
										9
		ļ								10
	-	-							-	11
	-									12
					<u> </u>					13
		<u></u>		1	<u> </u>		-			14
			1							15
	-									16
	-									17
	<u> </u>		<u> </u>		Appro	ed:				18
	1			<u> </u>	1	N 1		1	<u> </u>	19
			<u> </u>		Chief	Comro	pher –		_	20
		ļ			[Pile! -	734.2		21
					13	May	1982			22
			<u> </u>							23
			 					-		24
NOAA FORM 76-155 SUPERSEDES	<u> </u>		<u> </u>					72-769-56		25

APPROVAL SHEET FOR SURVEY H-9898

- A. All revisions and additions made on the smooth sheet during verification have been entered in the magnetic tape records for this survey. A new final position printout has AREXXXXXX been made. A new final sounding printout has/hasxxxxXX been made.
- B. The verified smooth sheet has been inspected, is complete, and meets the requirements of the <a href="https://www.hydro.com/hydro.com

Onief, Verification Branch

NOAA FORM (5-77)	77–27		Ļ	J. S. DEPARTME	NT OF COMMERCE	HYDROGRA	APHIC SURVEY NUM
	HYDROGE	RAPH	IC SURVE	Y STATISTIC	CS	H-	9898
	CCOMPANYING SU	IRVEY:	To be comple	ited when survey	is registered.		
	DESCRIPTION		THUOMA		RECORD DESCRIPT		AMOUNT
SMOOTH SHE			1	BOAT SHE	EETS & PRELIMINAL	RY OVERLAYS	5
DESCRIPTIV	E REPORT		1	SMOOTH C	OVERLAYS: POS. A	RC, EXCESS	3
DESCRIP- TION	DEPTH RECORDS		Z. CONT. ECORDS	PRINTOUTS	TAPE ROLLS	PUNCHED C	ABSTRACT SOURCE DOCUMENT
ENVELOPES							
CAHIERS				2 Ra	u		
VOLUMES							
BOXES				1 Pasé	SUMB. Plo, H	1 V/1	19. Min 10
T-SHEET PR				, ,,,,	7000 1 10)	LIGI. DINDE	ALCIU. II VOC. I CA
SPECIAL REP	ORTS (List)		OFFICE DE	CREETING :			
	The following s	tatistic	s will be subm	CESSING ACTIV	ITIES tographer's report on	the survey	
	PROCESSING	ACTIV	/ITY		DDF	AMOUNTS	
POSITIONS OF	N SHEET				PRE- VERIFICATION	VERIFICAT	ION TOTALS
POSITIONS	CHECKED					2242	2242
POSITIONS	REVISED					148	
SOUNDINGS RI	EVISED					96	148
SOUNDINGS EF	RRONEOUSLY SPA	ACED				740	96
SIGNALS (CON	TROL) ERRONEO	USLY F	PLOTTED			/40	740
						TIME - HOU	786
CRITIQUE OF	FIELD DATA PAG	CKAGE	(PRE-VERIF	ICATION)	10	36	46
VERIFICATION	N OF CONTROL					8	
VERIFICATION	OF POSITIONS					42	8
VERIFICATION	OF SOUNDINGS					213	42
COMPILATION	OF SMOOTH SHE	ET					213
	OF TOPOGRAPH				 	126	126
APPLICATION	OF PHOTOBATH	YMETR	Y			3	3 .
JUNCTIONS							
COMPARISON	VITH PRIOR SURV	EVS ^	CHARTS			2	2
VERIFIER'S RE		E 13 &	CHARIS			28	28
OTHER		·				14	14
		то	TALS		7.0	1,70	1,00
Pre-Verification	"byJ.Lehne	r. F	. Saunde	ne	10 Beginning Date _ ,	472	482
erification by	Bradford,	TIA	hnen F	Canada	⊥⊥/ Beginning Date	19/80 Endi	ng Date 11/20/80 ng Date
erification Che	Ck by H. R.	Smi	+p	saumaers	Time (House)	25/80 Date	ng Date 10/13/81
erine Center Inc	spection by		<u></u>		Time (Hours)	Date	9/8/81
uality Control I	H.I.		^ • • •		24		10/8/81
equirements Ev		<u> </u>	aunjar	dur	Time (Hours) Time (Hours)	82 Date	4/6/82
	Tup!		Iern			0. 0 Pate	12/82

5/6/82

REGISTRY NO. 9898

The magnetic tape containing the data for this survey has not been corrected to reflect the changes made during evaluation and review.

When the magnetic tape has been updated to reflect the final results of the survey, the following shall be completed:

MAGNETIC TAPE CORRECTED

DATE	TIME	REQUIRED	 INITIALS	• •
REMARKS:				

ATLANTIC MARINE CENTER VERIFICATION REPORT

Survey No.: H-9898 Field No.: WH-20-2-80

Michigan, Lake Huron, Port Sanilac to Lexington Heights

Surveyed: July 23 to October 9, 1980

Scale: 1:20,000 Project No.: OPR-XII5

Soundings: Ross Digital Echo Control: Argo (Range/Range)

Sounder, Raytheon
DE-719B Fathometer
Del Norte/Theodolite
(Range/Azimuth)

Lead-line

Chief of Party Frank P. Rossi
Surveyed by R. G. Mann
J. C. Gardner, Jr.
D. A. Bland
J. B. Grant
Automated Plot by Xynetics 1201 Plotter (AMC)

1. Introduction

- a. During verification of the survey a discrepancy of approximately two (2) feet was found between main scheme hydrography and some lines splitting main scheme hydrography. Main scheme hydrography was run between days 205 and 211. The splits were run after day 234. The fathograms were rescanned, water levels checked, and correctors checked to determine the cause with negative results. The splits were rejected and main scheme hydrography retained. The rejection of these data did not depreciate the results of this survey.
- b. A discrepancy was found with the velocity correctors on this survey. The field computations could not be correlated with the graphs provided by the field. New graphs were formulated using data taken from the NOAA Forms 77-44. New velocity tables were compiled and new correctors applied to the survey. As no significant difference resulted, the original survey data provided were used for velocity corrections.
 - c. Notes in the Descriptive Report were made in red during verification.

2. Control and Shoreline

- a. Control is adequately discussed in sections F and G of the Descriptive Report.
- b. Shoreline in Port Sanilac Harbor was applied in brown from NOS Chart 14862 (23rd Edition, July 29/78). No shoreline was applied to the 1:20,000 scale survey work because there are no existing shoreline manuscripts. Charted shoreline is at a scale of 1:120,000. Transfer of this shoreline is not practical due to scale difference between the chart and the survey.

3. Hydrography

- a. Soundings at crossings are in agreement. Depths vary from one (I) to two (2) feet.
- b. The standard depth curves could be adequately delineated. The twenty-four (24) foot curve was delineated because of the charted twenty-four (24) foot curve. The thirty-six (36) foot curve was used to delineate some isolated shoal features. Brown curves were used to show additional relief in some areas.
- c. The development of the bottom configuration and determination of least depths is considered adequate.

4. Condition of Survey

The smooth sheet and accompanying overlays, hydrographic records and reports are adequate and conform to the requirements of the <u>Hydrographic Manual</u> with the following exceptions:

- a. The hydrographer used the wrong edition of the chart for comparison.
- b. Section N of the Descriptive Report failed to mention the fixed aids to navigation in the survey area.
- c. The error mentioned in section D of the Descriptive Report was never brought to the attention of the Electronic Engineering Division during the inport period as mentioned.
- d. The averaging of bar check data and plotting of some bar check curves was marginal at best. Direct Comparison Logs were not submitted with the survey records nor were the computations for the TDC observations.
- e. The landmarks in the vicinity of Port Sanilac were not investigated, nor is there any data to corroborate the fact that the charted landmarks and existing landmarks are one in the same. The field scaled landmarks from USCG quad maps.

5. Junctions

Adequate junctions were affected with the following surveys:

H-9895 (1980) to the south / H-9899 (1980) to the west / for chart compilation use H-9899, 1:5,000 H-9906 (1980) to the north /

There were no contemporary surveys inshore of this survey north and south of H-9899 (1980), Lexington Harbor and the inset of Port Sanilac Harbor shown on this survey. The Lake Survey surveys in this area were considered prior surveys and are discussed below.

6. Comparison With Prior Surveys

LS-1847 (1:120,000) 1946 LS-1970 (1:10,000) 1956 LS-1971 (1:10,000) 1956 LS-1972 (1:10,000) 1956 LS-19723 (1:10,000) 1956 CHS SURVEY 3831 (1:100,000) 1974

The above prior surveys are the most recent prior surveys which taken together cover the common area of the present survey.

Comparison with prior surveys done by the U. S. Lake Survey showed good agreement. In general the prior surveys were from one (1) to five (5) feet shoaler than the present survey. Some prior survey soundings were brought forward to supplement the present survey.

The Canadian Hydrographic Survey, survey 3831 of 1974, is generally three (3) to five (5) feet shoaler than the present survey. The field unit experienced difficulty in junctioning with the Canadian survey. A letter, dated November 14, 1980, outlines a conversation between CO, WHITING, and Ross Douglas, CHS. A copy of this letter is included in the Descriptive Report. The present survey should be considered as superseding the Canadian survey in the common area. Not exclode during Q.C.

The present survey is adequate to supersede the prior U. S. Lake Survey surveys in the common area except where prior survey data were brought forward to supplement the present survey.

7. Comparison With Chart 14862 (23rd Edition, July 29/78)

a. Hydrography

The charted alongshore hydrography originates with the previously mentioned surveys and requires no further discussion.

The following charted features in Port Sanilac Harbor were neither verified or disproved by the present survey and come from unascertainable sources:

<u>Item</u>	<u>Latitude</u>	Longitude
Subm. 1) Wreck	43°25'48.5"N	82°32' 20. 0''W
2) Shoal	43 25 X 0"N	82 ⁰ 32'13.0"W
3) Rock	43 [°] 25′5 1 °0″N	82 ⁰ 32' 24 ':0"W
4) Rock	43 ⁰ 26'07.0"N	82 ⁰ 32' 20.0 "W

These should remain as charted unless subsequent information indicates differently.

The charted hydrography in Port Sanilac Harbor originates with the previously mentioned surveys and unasertainable sources and requires no further discussion.

The present survey except as noted above is adequate to supersede the charted hydrography in the common area.

b. Controlling Depths

The charted controlling depth for the entrance to Port Sanilac Harbor is nine (9) feet. The present survey has an eight (8) foot depth inside of the dashed dredging limits.

c. Aids to Navigation

Although the hydrographer states there are no floating aids to navigation, five (5) fixed aids are located within the survey area. Two (2) aids are in Lexington Harbor and three (3) are in Port Sanilac. These aids are adequate to serve their intended purposes.

8. Compliance With Instructions

The survey adequately complies with Project Instructions with the following exception: Section 4.2.1 (Shoreline & Charted Detail). See Section 7a. of this report.

9. Additional Field Work

This is an adequate basic survey, and no additional field work is recommended.

J. Scott Bradford

Cartographic Technician

Verification of Data

Harry R. Smith

Senior Cartographic Technician

Verification Check

Robert G. Roberson

Cartographer

Evaluation and Analysis

INSPECTION REPORT H-9898

The completed survey has been inspected by the Hydrographic Inspection Team with regard to survey coverage, delineation of depth contours, development of critical depths, cartographic symbolization, and verification or disproval of charted data. The Verification Report has presented the facts accurately and properly, the procedures used were appropriate, and the recommendations are logical and justifiable. The survey complies with National Ocean Survey requirements except as noted in the Verification Report. The survey records comply with NOS requirements except where noted in the Verification Report. The Hydrographic Inspection Team concurs with the verifier's findings, actions, and recommendations.

Karl Wm. Kieninger, COR, NOAA Chief, Processing Division

R. D. Sanocki Chief, Verification Branch Processing Division

James C. Gardner, J., LTJG, NOAA Chief, EDP/Branch

Chief, EDP/Branch Processing Division

Approved/Forwarded October 13, 1981

Examined and Approved

Hydrographic Inspection Team

Richard H. Houlder, RADM, NOAA Director, Atlantic Marine Center



UNITED STATES DEPARTMENT OF COMMERCE National Oceanic and Atmospheric Administration NATIONAL OCEAN SURVEY Rockville, Md. 20852

C352:SRB

April 6, 1982

TO:

Glen R. Schaefer

Chief, Hydrographic Surveys Division

THRU:

Chief, Quality Control Branch (

FROM:

50 Baumyaden S. R. Baumgardner

Quality Evaluator

SUBJECT:


Quality Control Report for H-9898 (1980), Michigan, Lake Huron, Port

Sanilac to Lexington Heights

A quality control inspection of H-9898 was accomplished to monitor the survey for adequacy with respect to data acquisition, delineation of the bottom, determination of least depths, navigational hazards, junctions, sounding line crossings, smooth plotting, shoreline transfer, decisions made and actions taken by the verifier, and the cartographic presentation of data. Revisions and additions to the smooth sheet, plus helpful comments made to the verifier, are identified on a one-half scale copy of the survey to be furnished the verifier. In general, the survey was found to conform to the National Ocean Survey's standards and requirements except as stated in the Verifier's Report.

cc: C351





Published at Washington, D. C.
U.S. DEPARTMENT OF COMMERCE
MATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SURVEY

Diagramo Ro. 13-5



UNITED STATES DEPARTMENT OF COMMERCE National Oceanic and Atmospheric Administration NATIONAL OCEAN SURVEY Rockville, Md. 20852

OCT 22 1982

Ween Hand

C351:SJY

TO:

CAM - Richard H. Houlder

FROM:

C3 - C. William Hayes

SUBJECT: H-9898 (1980), Michigan, Lake Huron, Port Sanilac to Lexington

Heights, Report of Compliance with Project Instructions

The smooth sheet and Descriptive Report for the subject survey have been examined. In addition to the Quality Control Report, dated April 6, 1982 (copy attached), and the Hydrographic Survey Inspection Team Report, dated October 13, 1981, the following is submitted:

Section K (Comparison with Prior Surveys) was not included in the Descriptive Report. The dangerous submerged wreck covered 13 feet and charted in latitude 43°15.7'N and longitude 82°30.6'W, originating from LS-1290 (1914), was not adequately investigated. A least depth should have been obtained by diver and the hydrographer should have recommended the charting action to be taken.

Except as noted, the survey is complete and adequate for the purposes intended and is in compliance with Project Instructions OPR-X115-WH/HSB-80, dated March 31, 1980.

Attachment

C352 w/o att.



RECORD OF APPLICATION TO CHARTS

FILE WITH DESCRIPTIVE REPORT OF SURVEY NO.

INSTRUCTIONS

A basic hydrographic or topographic survey supersedes all information of like nature on the uncorrected chart.

1. Letter all information.
2. In "Remarks" column cross out words that do not apply.
3. Give reasons for deviations, if any, from recommendations made under "Comparison with Charts" in the Review.

CHART	DATE	CARTOGRAPHER	REMARKS
4862	5-13-83	Dugan B. Nois	Full-Pare Before After Verification Review Inspection Signed Via
			Drawing No. 4 Resided several sudjs & revised several
			Curves
14860	5-14-B3	Shyan B. Nonis	Full Part Before After Verification Review Inspection Signed Via
		8	Drawing No. 6 Revised (6) and 35, 24/2 30' curves.
			Full Part Before After Verification Review Inspection Signed Via
		- 1887 LA	Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
, , , , , , , , , , , , , , , , , , , ,			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
		, *	
			Full Part Before After Verification Review Inspection Signed Via
			Drawing No.
			Full Deep Defeat Afree Verification Design Institute Circuit Vic
			Full Part Before After Verification Review Inspection Signed Via Drawing No.
		<u> </u>	·
· · ·			