

1649d

83
SHA
1649D
1905

Treasury Department,
U. S. COAST AND GEODETIC SURVEY.

O. H. Latham
Superintendent.

State: *Alaska*

DESCRIPTIVE REPORT.

Hyd. Sheet No. *1649d*

LOCALITY:

Clarence Strait;

*Vicinity of South
Vallenor Pt.*

1905

CHIEF OF PARTY:

C. F. Dickins, Commanding

U. S. C. & G. SURVEY,
LIBRARY AND ARCHIVES,
SEP 26 1905
Acc. No.

1649d

March 10, 1920.

MEMORANDUM

Hydrographic sheet 1649^d — *Still missing*

Clarence Strait, Vicinity of South Tailor Point, Alaska

By E. F. Dickins in 1905

The above sheet is missing from its tube.

It is a small sheet, (possibly a tracing.)

The divisions and sections noted below are requested to have a search instituted for it.

Chief, Division of Charts.

Hydrography & Topography

Field Work

Tides

Geodesy

Magnetics

Drafting

Field Reports

U. S. C. & G. SURVEY,
LIBRARY AND ARCHIVES,
SEP 26 1905
Acc. No.

REEF OFF SOUTH VALLENAR POINT,
CLARENCE STRAIT, S.E. ALASKA.

This reef lies about $3/4$ of a mile S. $1/4$ W. (mag) from the outer end of South Vallenar Point and consists of two distinct ledges, about 300 yards apart, with 8 fathoms of water in between them and deep water between them and the shore, both are marked by kelp.

The Northern reef is about 100 yards in extent with 12 feet of water over it, the Southern one is awash at extreme low tide and is not more than 30 yards in extent.

From the outer end of the reef Guard Island Light House bears N.N.W. $1/4$ W. (mag), the South tangent of Grindell Island bears W. $1/4$ S. and the North tangent of Chasina Point bears S. x W. $1/4$ W. (mag).

By keeping at least a mile off the point all danger will be avoided.

Respectfully submitted

E. F. Dickins

Assistant C. & G. Survey,

Commanding.

