2057

Diag. Cht. No. 8202-1

Department of Commerce and Labor COAST AND GEODETIC-SURVEY	
State: State: DESCRIPTIVE REPORT.	
Sheet No.	
LOCALITY:	
190	
CHIEF OF PARTY:	

いつので

Report on Hydrographic Sheet No. 2057.

The results of these examinations are satisfactory so far as Buford and Prosper Rocks are concerned, but for completeness the work should have covered the unsurveyed anchorage inside Buford Rock, Chilket Islands, and the undeveloped ridge of which Prosper Rock is a part.

Some difficulty was experienced in plotting the work on account of the method used in determining the position of signals.

12/13/05.

J.T. Watkins. (Signed).