## 3526

Diag. Cht. No. 1218-2

U. S. COAST AND GEODETIC SURVEY

DEPARTMENT OF COMMERCE

### DESCRIPTIVE REPORT

Type of Survey HYDROGRAPHIC Field No. H-3526 LOCALITY DELAWARE General locality \_\_\_\_\_\_DELAWARE\_BAY\_ Locality DELAWARE BREAKWATER, HARBOR OF REFUGE 19413 CHIEF OF PARTY P. C. Whitney LIBRARY & ARCHIVES

DATE SEPTEMBER, 15, 1913.

B-1870-1 (1)

74 3526

C. & G. SHRVEY, SEP 15 1913

General Locality: Cape Henlopen, Delaware

Special Locality: Inner and Cuter Harbors, Delaware Breakwater

Chief of Party: Paul C. Whitney, Assistant, Shore Party

Date: August 2nd to 14th, 1913

Scale: 1/10000

# 3526

Discriptive Report to accompany

Hydrographic Sheet

Resurvey Inner and Cuter Harbors

Delaware Breakwater

August 1913

Paul C. Whitney

Chief of Party

Scale 1/10000

The hydrography included on this sheet comprises an area laid down for a resurvey, by Acting Inspector of Hydrography and Topography.

the sheet was furnished, with the plotted points, by the Office. One new point was determined, that of the light at the west end of the inner breakwater, by sextent angles, which are recorded in volume one, mpage 16.

The development was carried to what was thought sufficient, with cross lines on a line parallel to the black and red buoys, to more fully develop Marshall and Norman Shoals. Asounding of 12 feet was obtained on the latter. Between the two breakwaters the botton is very uneven and especially so near the shoals.

All the buoys were found out of their positions, as laid down on the present chart, although at present the Marshall Shoal buoy indicates the position of the least water there.

The present condition of the wharves along the shore are noted and the new ones since the last survey placed on from sextent angles.

Considerable difficulty was attended running lines at a distance out and west of the breakwater. No ranges could be picked up and tidal currents ran with considerable velocity. There are a couple bad spacings, that showed up better on the boat sheet, otherwise an endeavor would have been made to split them.

It was the intention to run some lines off Cape Henlopen, but the sea was always so rough the last week it had to be given up.

Tides were read on a staff erected at the Queen Ann R. R. Pier. This staff was connexted by levels to the various Bench Marks in the vicinity. This work is made the subject of a separate report in accordance with Supplementary instructions of July 28, 1913.

The survey was made in accordance with instructions of July 25. 1913.

Respectfully submitted,

Paul Chief of Party, C. & G.

#### STATISTICS

C. & G. SERVEY, LIBRARY AND AROBIVES SEP 15 1913 Acc. No.

To accompany Hydrographic Sheet of

The Inner and Cuter Harbors at the Delaware Breakwaters,
Delaware
1913

Da	te	Vol.	Letter	Positions	Soundin	gs Miles	Beat Rer	marks
Aug	. 2	1	a	46	226	6.5	Launch	
77	4	1	ъ	126	598	17.2	11	
11	5	1	C	64	304	8.5	11	63
11	6	1	đ	155	569	22.5	11	CIE
<b>†1</b>	7	2	е	123	499	13.2	11	
*1	8	2	f	127	612	21.0	11	13.3
11	9	2	g	53	245	9.0	11	
11	12	2	h	73	285	6.0	11	P. 9
11	13	3	j	103	472	12.6	n	
11	14	3	k	13	79	1.3	. 11	
		T	otals 3 Vol	s 883	3889	117.8		· • •

Tide Gauges.

The Tide Gauge was located on the Queen Ann R.R. Pier at Lewes, Delaware and is to be used for all of this work.

Plane of reference is 5.1 ft. above the zero of staff.

Lowest tide observed read 4.8 ft. on staff.

Highest tide observed read 10.3 ft. on staff.

#### HYDROGRAPHIC BHEET 3526.

Breakwater Harbor, Delaware, by Assistant P. C. Whitney in 1913.

#### TIDES.

·			Lewes
			ft.
Mean low water, or referen	plane ce on	of staff	5.1
Lowest tide observe	d "	11	2.2
Highest " "	11	Ħ	13.7
Mean range of tide	`		4.3

H. 3526.

Harbor of Refuge Delaware Bay. Very good sheet.

Sheet examined in Div. of Hyd'y & Top'y.

### Hyd. Sheet No 3526

Within the limits of the work, the ground is well covered and the development sufficient.

All though there are not many cross lines, there is an average variance or differing in the soundings, of from two to seven feet. This is due more to the roughness of the water than to any errors or carelessness in the work.

The twenty four foot spot, shown on Hyd Sheet No 2653, and question marked, evidently does not exist and ought not to be charted.

Ahere This work over lapps previous surveys, it agrees very well.

R.L.Johnson Dec. 1913.

Plotted by field farty. Verified + inked by P.L.J.

Soundings expressed in feet.