

Final Tidal Zoning for OPR-P151-RA-200

Jack Bay, AK - Sheet H11267

NOTE B
The area outlined in magenta is a National Marine Fisheries Service monitoring site. Marine activities are discouraged from infringing into the area.

945-4240 VALDEZ

PWS67
Time Corrector 0 mins
Range Corrector x0.99
Reference 945-4240

CAUTION
Significant changes in depths and shoreline may have occurred in the area of this chart as a result of the earthquake of March 27, 1964. Tidal observations since the earthquake indicate bottom uplift of 4-4.3 feet at Port Gravina. Mariners are urged to use extreme caution when navigating in the area of this chart as the magnitude of change except in Port Valdez and Tatlielik Narrows is not known. Important changes from geodetic surveys of these two areas are charted.

The U.S. Coast Guard Services (VTS) system operating procedures frequencies are published in the VTS Manual. Mariners are urged to consult these sources for requirements. Although limited to the navigation of certain vessels are in condition of port entry traffic management.

