3881

Diag. Cht. No

Mark -
Nantucket Shoals
Pollock Rip Slue

3881
3881
3881

LIBRARY
Place with descriptive report
of hydrographic sheet No. 3881
GLF
Drawing Section.

Examination of Pollock Rip Slue

This work is hardly close enough to be of much use.
The curves can only be indicated in spots.
A 13 ft. sounding half way between pos. 19 and pos. 20, could not be plotted as pos 19 was obviously wrong and was rejected.
The 12 ft. sounding between pos. 35 and pos. 36, appears doubtful.
The buoys should have been located.

R. L. Johnston

Position 19a cannot be reconciled therefore the position of the 13 ft sounding is only approximate as marked. It may be that this 13 ft sounding and the 12 ft sounding on line 35-36 are both 2 fathoms too small.

John D. Tenney
7/17/16

Soundings in feet.

Protracted, plotted & inked by R.L.J.
Verified 7/17/16 " J.D.T.