
70°43'W
70°42'W
70°41'W
70°40'W
43° 04' N
43° 03' N
43° 02' N
43° 01' N
Kittery Point
by Pepperrell Cove Buoy 5
by Pepperrell Cove Buoy 3
Pepperrell Cove
Pepperrell Cove Anchorage Area
by Pepperrell Cove Buoy 2
Phillips Island
Gooseberry Island
by Fishing Island Ledge Buoy 4
Fishing Island
Portsmouth Harbor
267 deg
by Cod Rock Lighted Buoy 5
Fl(1)G 4s
Salamander Point
Fort Point
Portsmouth Harbor (New Castle) Light
New Castle Island
by Stielman Rocks Buoy 3
bn Stielman Rocks Daybeacon 3A
Wood Island
Horn Island
Sewards Cove
Sisters Point
West Sister
by West Sister Buoy 2
by Wood Island Lighted Buoy 2
Fl(1)R 4s
White Island
Whaleback Light
353 deg
Jaffrey Point
by Little Harbor Buoy 6
Little Harbor
by Little Harbor Buoy 5
bn Jaffrey Point Light 4
Fl(1)R 4s6.7m4M
by Little Harbor Entrance Buoy 2
Frost Point
by Little Harbor Entrance Buoy 1
by Kittery Rocks Lighted Whistle Buoy KR
Odiornes Point
Big Cove Bight
by Gunboat Shoal Lighted Bell Buoy 1
Fl(1)G 4s
Gunboat Shoal
NOT FOR NAVIGATION
NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
NATIONAL OCEAN SERVICE
OFFICE OF COAST SURVEY
ESD-PHB-20, W00507
Coastal New Hampshire, NH
Approaches to Portsmouth Harbor
REMARKS:
– Depths in Meters
– Additional data and products for this survey available https://www.ncei.noaa.gov
– Isolated features such as rocks, wrecks, and obstructions are not portrayed on this product
– Read attached W00507_read_me.txt for additional information