

H 1334 a (1875-6)

That portion of H-1334a that falls within the limit of H-1333a (1875-6) should not be used for charting for the following reasons:

1. part of the controls for the western half of the sheet are beyond the limit of the sheet and numerous ~~lines~~ soundings have been found to be plotted 100 to 200 meters ~~different~~ from the position as shown on H-1333a.
2. all of the sounding lines shown on # H-1333a are not shown on H-1334a.
3. a different and inferior selection of soundings have been plotted on H-1334a, (which often fails to include the least depths as recorded in the volumes).

Ladd July 12, 1935