

2706

83  
SHA  
2706  
1904

Diag. Cht. No. 77-2

Treasury Department,  
U. S. COAST AND GEODETIC SURVEY.

*O. N. Tittmann*

Superintendent.

State: *Md. & Va.*

U. S. C. & G. SURVEY,  
LIBRARY AND ARCHIVES,

MAR 14 1905

Acc. No.

DESCRIPTIVE REPORT.

*Hydro. Map*

Sheet No. *2706*

LOCALITY:

*Potomac River;*

*Maryland Point to*

*Aquia Creek.*

1904

CHIEF OF PARTY:

*J. B. BOUTELLE, ASST.*

2706

Descriptive Report -  
Hydrographic Sheet -  
Potomac River - Aquia Creek to Maryland Pt.  
1904

---

Progress of Potomac River - This sheet was but partially completed owing to work having been stopped by ice in the river.

The channel is supposed to have been dredged to 24 feet but the present survey shows only a very narrow and crooked channel of this depth between Red Spar buoy #12 C and R.S. buoy #12 1/2. More work is necessary for a complete development of this channel.

About 150 meters S.W. of B.S. buoy #19 is a 12 3/4 foot spot not shown on the published chart. This spot needs more development.

A 14 ft. spot about 750 meters S.W. of B.S. buoy #21 is probably an error of 1 fathom as the bottom is generally flat and even in this vicinity.

J. D. Douthett  
Assistant, C. & G. Survey  
Chief of Party.

Report  
on  
Hydrographic Sheet  
No. 2708.  
Potomac River,  
Maryland Point to Aquia Creek,  
Md. and Va.  
Assistant Boutelle,  
1904.

The plotting was well done and the records well kept.

The lines do not cross well.

The field work on this sheet has not been completed.

11/1/05.

H. L. Simons. (Signed).