

I. INTRODUCTION

a. No tide reducers were applied to 19 soundings shoaler than 100 fathoms in the vicinity of Latitude $17^{\circ}38'10''$, Longitude $64^{\circ}54'35''$. With a tidal range of only .1 fathom in this area, it was felt during verification that the sounding valves would not be significantly affected by not applying the tide reducers. No other unusual problems were encountered during verification.