

Based on previous feedback, Leidos has not submitted a Horizontal and Vertical Control Report for surveys that did not require vertical control stations to be installed or recovered and/or horizontal control station installed. Instead we have included a Readme.txt file in the Horizontal\_&\_Vertical\_Control\_Report folder stating along the lines of: “No vertical or horizontal controls were established, recovered, or occupied during the survey. Vertical and horizontal control specifics are discussed in each sheet's DR.”

For OPR-K371-KR-17 no vertical or horizontal control stations were installed, recovered or occupied. However, we wanted to confirm with you that this is still acceptable for OPR-K371-KR-17 to not deliver a HVCR.