

2291

Diag. Cht. No. 5530-3

U. S. C. & G. SURVEY.

LIBRARY AND ARCHIVES.

JAN 31 1900

U. S. COAST AND GEODETIC SURVEY

Abot. No.
KEY.

Superintendent.

State: *California*

DESCRIPTIVE REPORT.

Hydrographic Sheet No. 2291

LOCALITY:

*Examination of
Buoy in connection with
Centissima Rock. Report made
to J. J. Silburt.*

18 96

CHIEF OF PARTY:

F. Westdahl

2291

Exact copy of page of record used in determining
buoys in the Bonita Channel on Dec. 22, 1896.

Note The tug was cruising about the locality and soundings were continually made. The observers were ready to take angles on the instant any shoal spot was found, but nothing more was recorded than here shown.

Ferdinand Westdahl

(Locality)

SOUNDINGS

Year 1896 Month Dec. Day of Month 22

TIME.	SOUNDINGS.		RED. FOR TIDE.	REDUCED SOUNDINGS.		BOTTOM.
	FEET.	TENTHS.		FEET.	TENTHS.	
	Fathoms.	Feet.	Feet.	Fathoms.	Feet.	
h. m. s. 12.00						
1.00	7	0	(approx)			
1.30	9	0				
3.00	6	0				

(Sub-Locality)

J. Westdahl & C. B. French, Owners

(Boat used)

day

ANGLES AND RANGES.

REMARKS.

Black No. 3

At 10 metres S.E. from Buoy 1

69.57 Cliff Ho. to Lagoon Pt.
129.01 Lagoon Pt. to Rocky Pt.

at 5 metres E. from Buoy Black No. 3
45.43 Bonita Lt. Ho. to Lagoon Pt.
142.03 Lagoon Pt. to tang. Duxbury Pt.

At 5 metres E. from Buoy Red No. 2

79. 29 Pt. Bonita Lt. Ho. to Ten. Valley Pt.
83. 53 Ten. Valley Pt. to Rocky Pt.

At spot (approx) where the Pilot thought
the ship struck

35.18 Bonita Lt. Ho. to Lagoon Pt.
141.44 Lagoon Pt. to Rocky Point

41.48 Samr
139.18