


Final Tidal Zoning for OPR-O340-RA-99

Lynn Canal, AK - Sheet H-10864



LOCAL MAGNETIC DISTURBANCE

Extreme magnetic disturbance exists in Port Snettisham and Gilbert Bay. The magnetic compass should not be relied upon within the area outlined in magenta.

Elsewhere, differences from the normal variation have been observed as follows:

Chilkoot and Chilkat Inlets	20°
Gastineau Channel in vicinity of Lat. 58°15'N.	5°
Tenakee Inlet, near Conroy Point	3°
North Passage of Lemesleul Island	7°
George Island at head of Granite Cove	3°
Entrance to Rendu Inlet	5°

SEA70
 Time Corrector 0 mins
 Range Corrector x1.01
 Reference 9452346

SEA68
 Time Corrector 0 mins
 Range Corrector x1.00
 Reference 9452346

SEA65
 Time Corrector 0 mins
 Range Corrector x0.99
 Reference 9452346

CAUTION

Shoaling amounting to as much as 6 feet has been disclosed in several critical shoal areas, from Cross Sd. to Excursion Inlet. It is probable that the Alaska Earthquake of July 10, 1958 created these shoalings and others not yet discovered. Mariners are urged to use caution when navigating over or near critical depths.

9452346 COVE POINT, BERNERS BAY

Survey Limits H-10864, Sheet T, RA-20-01-99

by Presidential Proclamation 5928, S. contiguous zone for the application defined as the outer limit of the territorial does not alter existing State or Federal Texas, the Gulf coast of Florida, and within the inner boundary of the Federal under the Submerged Lands Act (P.L. limits are subject to modification, as recent chart edition take precedence.

note A) ions at Sec. 1972. COLREGS Demarcation Line.

