



13 SPECIAL ANCHORAGE 110.1, 110.60 (see note A)

SAFETY ZONE 165.T01-0174 (see note A)

REGULATED NAVIGATION AREA 165.T01-0174 (see note A)

NO DISCHARGE ZONE (see note Z)

CAUTION Fixed and floating obstruction submerged, may exist between the buoys upstream and downstream from the bridge. Mariners are advised to proceed with caution.

**NOT FOR NAVIGATION**

NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION  
NATIONAL OCEAN SERVICE  
OFFICE OF COAST SURVEY

**OPR-B396-NRT5BH2-17, H13092**  
Hudson River, NY  
Piermont Pier to South of Ossining

REMARKS:  
- Depths in Feet  
- Additional data and products for this survey available <http://www.ngdc.noaa.gov>  
- Isolated features such as rocks, wrecks, and obstructions are not portrayed on this product  
- Read attached H13092\_read\_me.txt for additional information