


NOT FOR NAVIGATION



S-B930-NRT5-17, D00243

East River, New York
East River Near Pier 11

REMARKS:
- Depths in Feet
- Additional data and products for this survey available <http://www.ncei.noaa.gov>
- Isolated features such as rocks, wrecks, and obstructions are not portrayed on this product
- Read attached D00243_read_me.txt for additional information

Temporary changes or defects in aids to navigation are not indicated on this chart. See Local Notice to Mariners.
During some winter months or when endangered by ice, certain aids to navigation are replaced by other types or removed. For details see U.S. Coast Guard Light List.

CAUTION
Broken lines are particularly at the edges.
RADAR REFLECTORS
Radar reflectors have been placed on many floating aids to navigation. Individual radar reflector identification on these aids has been omitted from this chart.

