2003 FIELD and FINAL TIDE NOTE Hydrographic Sheet: H11236 Sheet B

Twenty Fathom Bank to Skowl Point Kasaan Bay, Alaska

NOAA Project (No:	OPR-0331-KR-2003	Kasaan Bay, Alaska		
NOAA Contrac		50-DGNC-0-90003			
The NOS Ketch	nikan, AK tide station (9	45-0460) served as	control for the subordina	te stations on thi	s project.
			te stations: Saltery Cove		
	5-0544). The NTDE 198				
Location and	Name:	Lat (NAD83)	Long(NAD83)	Time Meridian:	
Time Meridian	Saltery Cove	55° 24° 07"	132° 19' 53"	0° (UTC)	
	Hollis Anchorage	55" 28' 45"	132" 38' 30"	0° (UTC)	
Time Period	Name:	Established:	Removed:	MLLW	MHW
and Datum	Saltery Cove	7/17/2003	9/3/2003	0.000 m	4.472 m
Reference	Hollis Anchorage	8/12/2003	9/1/2003	0.000 m	4.584 m
	Terra Surveys, LLC 1930 South Whiting Ci Palmer, Alaska 99645 (907) 745-7215	rcle			
Gauges	Design Analysis Ass. H350XL/355 bubbler systems.				
Install Type		red inside a waterord	of case, and fastened w	ertically inside of	an enclosed
	Rubbermaid garden to installation. No tide staff was instal	olshed. Refer to the led. Levelling was p	of case, and fastened ve tide station package for a erformed from a tidal ber od with a stilling well atta	additional site sp nch mark to the v	vater surface.
Tide Staff	Rubbermaid garden to installation. No tide staff was instal	olshed. Refer to the led. Levelling was p	tide station package for a	additional site sp nch mark to the v	vater surface.
	Rubbermaid garden to installation. No tide staff was install The water height was in from waves. The following bench m Satery Cov Hollis Anch The following bench m Satery Cov	oished. Refer to the led. Levelling was p read using a metric r arks were installed a re; none orage; none arks were recovered re; BM 2 1921, BM 3	tide station package for a erformed from a tidal ber od with a stilling well atta at these sites:	additional site sp nch mark to the v sched to remove	ecific details of vater surface, interference
Tide Staff Bench Marks Levels	Rubbermaid garden to installation. No tide staff was install The water height was inform waves. The following bench m Satery Cov. Hollis Anch. The following bench m Satery Cov. Hollis Anch. Bench marks were lew and station datums we closed within NOS tole.	oished. Refer to the led. Levelling was pread using a metric rarks were installed a re; none orage; none arks were recovered re; BM 2 1921, BM 3 orage; BM 1 1924, I elied at the installative connected throughance.	erformed from a tidal ber od with a stilling well atta at these sites: 1921, BM 4 1958, BM 5 3M 2 1924, BM 3 1924, B in and removal of the tid th frequent water level me	additional site sp nch mark to the v sched to remove is 1958, BM 6 196 BM 4 1953, BM 5 all stations. The l	vater surface, interference
Tide Staff Bench Marks Levels	Rubbermaid garden to installation. No tide staff was install The water height was in from waves. The following bench m Saltery Cov. Hollis Anch The following bench m Saltery Cov. Hollis Anch Bench marks were lew and station datums we	oished. Refer to the led. Levelling was pread using a metric rarks were installed a re; none orage; none arks were recovered re; BM 2 1921, BM 3 orage; BM 1 1924, I elied at the installative connected throughance.	erformed from a tidal ber od with a stilling well atta at these sites: 1921, BM 4 1958, BM 5 3M 2 1924, BM 3 1924, B in and removal of the tid th frequent water level me	additional site sp nch mark to the v sched to remove is 1958, BM 6 196 BM 4 1953, BM 5 all stations. The l	vater surface, interference
Tide Staff Bench Marks Levels	Rubbermaid garden to installation. No tide staff was install The water height was inform waves. The following bench m Satery Cov. Hollis Anch. The following bench m Satery Cov. Hollis Anch. Bench marks were lew and station datums we closed within NOS tole.	oished. Refer to the led. Levelling was pread using a metric rarks were installed a re; none orage; none arks were recovered re; BM 2 1921, BM 3 orage; BM 1 1924, I elied at the installative connected throughance.	erformed from a tidal ber od with a stilling well atta at these sites: 1921, BM 4 1958, BM 5 3M 2 1924, BM 3 1924, B in and removal of the tid th frequent water level me	additional site sp nch mark to the v sched to remove is 1958, BM 6 196 BM 4 1953, BM 5 all stations. The l	vater surface, interference
Tide Staff Bench Marks Levels Final Tidal Zoning	Rubbermaid garden to installation. No tide staff was install The water height was inform waves. The following bench m Satery Cov. Hollis Anch. The following bench m Satery Cov. Hollis Anch. Bench marks were lew and station datums we closed within NOS tole. This sheet is covered by the station data are.	oished. Refer to the led. Levelling was pread using a metric rearks were installed a re; none crage; none arks were recovered re; BM 2 1921, BM 3 orage; BM 1 1924, it elied at the installative connected through rance. By zone SA100 and duced to MLLW and duced to MLW and	erformed from a tidal ber od with a stilling well attact these sites: If at these sites: If 21, BM 4 1958, BM 5 BM 2 1924, BM 3 1924, BM 3 1924, BM 3 1934, BM 5 BM	additional site sp ach mark to the v sched to remove is 1958, BM 6 196 BM 4 1953, BM 5 all stations. The leasurements. The	ecific details of vater surface, interference interference 59 5 1960 bench marks the level runs omial curve fit.
Tide Staff Bench Marks	Rubbermaid garden to installation. No tide staff was install The water height was inform waves. The following bench m Satery Cov. Hollis Anch. The following bench m Satery Cov. Hollis Anch. Bench marks were lew and station datums we closed within NOS tole. This sheet is covered by the station data are.	oished. Refer to the led. Levelling was pread using a metric rearks were installed a re; none crage; none arks were recovered re; BM 2 1921, BM 3 orage; BM 1 1924, it elied at the installative connected through rance. By zone SA100 and duced to MLLW and duced to MLW and	tide station package for a erformed from a tidal ber od with a stilling well atta at these sites: 1921, BM 4 1958, BM 5 BM 2 1924, BM 3 1924, B in and removal of the tid in frequent water level me SA38.	additional site sp ach mark to the v sched to remove is 1958, BM 6 196 BM 4 1953, BM 5 all stations. The leasurements. The	vater surface, interference 59 51960 bench marks he level runs
Tide Staff Bench Marks Levels Final Tidal Zoning Reduction of	Rubbermaid garden to installation. No tide staff was install The water height was inform waves. The following bench m Satery Cov. Hollis Anch. The following bench m Satery Cov. Hollis Anch. Bench marks were lew and station datums we closed within NOS tole. This sheet is covered by the same was provided to Telegraphics.	dished. Refer to the led. Levelling was pread using a metric rearks were installed a re; none crage; none arks were recovered by 2 1921, BM 3 orage; BM 1 1924, it elied at the installative connected through rance. By zone SA100 and duced to MLLW and erra Surveys, LLC (grand series and series surveys, LLC (grand series serie	erformed from a tidal ber od with a stilling well attact these sites: If at these sites: If 21, BM 4 1958, BM 5 BM 2 1924, BM 3 1924, BM 3 1924, BM 3 1934, BM 5 BM	additional site sp inch mark to the v sched to remove is 1958, BM 6 196 BM 4 1953, BM 5 all stations. The li easurements. The	vater surface, interference 59 51960 bench marks he level runs