

characteristics:
 bld boulders Co coral gy gray
 bk broken G gravel h hard
 cy clay Grs grass M mud


R Bn radiobeacon Y yellow

Oys oysters
 Rk rock
 S sand

so soft
 Sh shells
 sy sticky

aneous:
 AUTH authorized
 ED existence doubtful
 1) Wreck, rock, obstruction, or shoal swept clear to the depth indicated.
 2) Rocks that cover and uncover, with heights in feet above datum of soundings.

Obstn obstruction
 PA position approximate
 PD position doubtful
 Rep reported
 Subm submerged



2008

53° 57' N

53° 57' N

NOT FOR NAVIGATION

NATIONAL OCEANIC AND ATMOSPHERIC ADMINISTRATION
 NATIONAL OCEAN SERVICE
 OFFICE OF COAST SURVEY

OPR-Q328-FA-16
 Unalaska Island, Alaska
 Vicinity of Eider Point and Wide Bay

REMARKS:
 - Depths in Fathoms
 - Additional data and products for this survey available <http://www.ncei.noaa.gov>
 - Isolated features such as rocks, wrecks, and obstructions are not portrayed on this product
 - Read attached H12939_read_mxtxt for additional information.

166°39'W

166°36'W

166°33'W